

Master copy

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
1	E 1500 NORTH ST	1	19	12	38	Alligator	Mill & Overlay	\$27,237.15	36	240.5
2	E 1500 NORTH ST	21	99	12	38	Alligator	Mill & Overlay	\$22,652.48	36	200.0
3	N 4500 WEST ST	0	0	214	90	Weathering	Slurry Seal	\$56.92	20	28.3
4	N 4500 WEST ST	10551	10599	214	90	Weathering	Slurry Seal	\$552.64	34	161.9
5	N 4730 WEST ST	0	0	214	90	Weathering	Slurry Seal	\$50.49	20	25.1
6	N 4730 WEST ST	10291	10299	211	70	Long/Trans	Chip Seal	\$2,101.30	34	160.1
7	N 4730 WEST ST	10301	10369	211	70	Long/Trans	Chip Seal	\$5,953.70	34	453.7
8	N 5100 WEST ST	11001	11099	131	75	Long/Trans	Slurry Seal	\$27,756.09	34	614.3
9	N 5100 WEST ST	11101	11199	131	75	Long/Trans	Slurry Seal	\$31,780.07	34	703.3
10	N 5250 WEST ST	10701	10749	218	80	Depressions	Do Nothing	\$0.00	34	284.4
11	N 5250 WEST ST	10751	10799	218	80	Depressions	Do Nothing	\$0.00	34	285.6
12	N 5250 WEST ST	10801	10849	218	80	Depressions	Do Nothing	\$0.00	34	308.0
13	N 5250 WEST ST	10851	10899	218	80	Depressions	Do Nothing	\$0.00	34	313.8
14	N 5250 WEST ST	10901	10925	218	80	Depressions	Do Nothing	\$0.00	34	143.8
15	N 5300 WEST ST	10551	10609	146	68	Long/Trans	Chip Seal	\$1,041.55	34	157.1
16	N 5300 WEST ST	10661	10683	146	68	Long/Trans	Chip Seal	\$1,041.56	34	157.1
17	N 5300 WEST ST	11131	11199	132	50	Alligator	Overlay	\$60,384.73	25	525.9
18	N 5320 WEST ST	10701	10799	227	78	Long/Trans	Slurry Seal	\$1,947.03	52	220.7
19	N 5370 WEST ST	10551	10609	146	68	Long/Trans	Chip Seal	\$2,334.19	34	352.0
20	N 5370 WEST ST	10611	10659	146	68	Long/Trans	Chip Seal	\$1,723.96	34	260.0
21	N 5470 WEST ST	10481	10599	147	80	Long/Trans	Slurry Seal	\$1,250.90	34	333.3
22	N 5470 WEST ST	10481	10599	146	68	Long/Trans	Chip Seal	\$2,113.53	34	318.7
23	N 5470 WEST ST	10601	10613	146	68	Long/Trans	Chip Seal	\$2,648.42	34	399.4
24	N 5470 WEST ST	10615	10621	146	68	Long/Trans	Chip Seal	\$1,041.03	34	157.0
25	N 5480 WEST ST	10031	10079	207	78	Pothole	Do Nothing	\$0.00	34	339.8
26	N 5480 WEST ST	10081	10129	207	78	Pothole	Do Nothing	\$0.00	34	319.1
27	N 5480 WEST ST	10131	10179	207	78	Pothole	Do Nothing	\$0.00	34	337.2
28	N 5480 WEST ST	10181	10185	207	78	Pothole	Do Nothing	\$0.00	34	208.4
29	N 5500 WEST ST	11001	11059	133	78	Block	Slurry Seal	\$1,661.25	34	415.4
30	N 5500 WEST ST	11061	11199	133	78	Block	Slurry Seal	\$3,585.39	34	896.6
31	N 5500 WEST ST	11201	11249	124	70	Weathering	Chip Seal	\$6,513.68	34	342.4
32	N 5500 WEST ST	11251	11349	124	70	Weathering	Chip Seal	\$13,704.44	34	720.4
33	N 5520 WEST ST	9751	9769	198	70	Long/Trans	Chip Seal	\$5,591.02	34	208.6
34	N 5520 WEST ST	9771	9789	198	70	Long/Trans	Chip Seal	\$4,210.58	34	157.1
35	N 5550 WEST ST	10601	10609	146	68	Long/Trans	Chip Seal	\$2,834.12	34	427.4
36	N 5550 WEST ST	10611	10619	146	68	Long/Trans	Chip Seal	\$1,041.58	34	157.1
37	N 5550 WEST ST	11001	11199	133	78	Block	Slurry Seal	\$5,234.67	34	1309.1
38	N 5580 WEST ST	9735	9759	198	70	Long/Trans	Chip Seal	\$4,210.61	34	157.1
39	N 5580 WEST ST	9761	9789	198	70	Long/Trans	Chip Seal	\$7,919.10	34	295.4
40	N 5600 WEST ST	0	0	38	58	Alligator	Chip Seal	\$6,191.06	44	223.1
41	N 5600 WEST ST	10025	10029	41	86	Weathering	Slurry Seal	\$501.87	30	160.8
42	N 5600 WEST ST	10031	10079	41	86	Weathering	Slurry Seal	\$1,070.18	30	342.9
43	N 5600 WEST ST	10081	10129	41	86	Weathering	Slurry Seal	\$978.18	30	313.4
44	N 5600 WEST ST	10131	10149	41	86	Weathering	Slurry Seal	\$535.68	30	171.6
45	N 5600 WEST ST	10151	10179	41	86	Weathering	Slurry Seal	\$524.15	30	167.9

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
46	N 5600 WEST ST	10181	10185	40	99	Patching	Do Nothing	\$0.00	42	639.4
47	N 5600 WEST ST	10181	10185	41	86	Weathering	Slurry Seal	\$683.61	30	219.0
48	N 5600 WEST ST	10181	10185	40	99	Patching	Do Nothing	\$0.00	30	582.0
49	N 5600 WEST ST	10401	10479	39	58	Aligator	Chip Seal	\$21,704.54	32	527.4
50	N 5600 WEST ST	10481	10569	39	58	Aligator	Chip Seal	\$17,284.40	32	420.0
51	N 5600 WEST ST	10481	10569	39	58	Aligator	Chip Seal	\$18,672.28	45	322.6
52	N 5600 WEST ST	10571	10679	39	58	Aligator	Chip Seal	\$16,280.56	32	395.6
53	N 5600 WEST ST	10571	10679	39	58	Aligator	Chip Seal	\$4,051.03	45	70.0
54	N 5600 WEST ST	10681	10769	38	58	Aligator	Chip Seal	\$10,471.80	44	377.3
55	N 5600 WEST ST	10771	10799	38	58	Aligator	Chip Seal	\$10,281.35	44	370.4
56	N 5600 WEST ST	10801	10873	38	58	Aligator	Chip Seal	\$7,045.07	44	253.8
57	N 5600 WEST ST	10875	10929	38	58	Aligator	Chip Seal	\$16,300.47	44	587.3
58	N 5600 WEST ST	10931	10999	38	58	Aligator	Chip Seal	\$13,286.85	46	457.9
59	N 5600 WEST ST	11031	11199	37	80	Long/Trans	Slurry Seal	\$3,413.85	34	954.5
60	N 5600 WEST ST	11031	11199	37	80	None	Slurry Seal	\$0.00	35	331.0
61	N 5600 WEST ST	11201	11269	122	48	Aligator	Overlay	\$76,721.88	34	564.4
62	N 5600 WEST ST	11271	11349	122	48	Aligator	Overlay	\$64,445.02	34	474.1
63	N 5630 WEST ST	11351	11369	122	48	Aligator	Overlay	\$26,821.69	34	197.3
64	N 5630 WEST ST	11371	11399	122	48	Aligator	Overlay	\$21,350.37	34	157.1
65	N 5650 WEST ST	9601	9749	197	68	Long/Trans	Chip Seal	\$28,611.50	29	1004.0
66	N 5650 WEST ST	9751	9799	197	68	Long/Trans	Chip Seal	\$11,189.69	24	474.5
67	N 5650 WEST ST	11031	11199	134	78	Long/Trans	Slurry Seal	\$4,165.36	34	1127.3
68	N 5660 WEST ST	10621	10649	149	90	Weathering	Slurry Seal	\$363.53	34	106.3
69	N 5660 WEST ST	10621	10649	149	90	Weathering	Slurry Seal	\$537.40	34	157.1
70	N 5680 WEST ST	9971	10029	203	99	Patching	Do Nothing	\$0.00	30	267.3
71	N 5680 WEST ST	9971	10029	201	90	Patching	Slurry Seal	\$668.91	34	190.5
72	N 5680 WEST ST	10101	10189	203	99	Patching	Do Nothing	\$0.00	30	571.6
73	N 5710 WEST ST	11201	11349	122	48	Aligator	Overlay	\$137,460.01	34	1011.3
74	N 5710 WEST ST	11351	11379	122	48	Aligator	Overlay	\$25,734.61	34	189.3
75	N 5710 WEST ST	11381	11389	122	48	Aligator	Overlay	\$21,350.54	34	157.1
76	N 5720 WEST ST	10621	10679	149	90	Weathering	Slurry Seal	\$907.01	34	263.6
77	N 5720 WEST ST	10621	10679	225	60	Bumps	Overlay	\$14,643.28	34	215.3
78	N 5720 WEST ST	10681	10769	225	60	Bumps	Overlay	\$22,847.95	34	336.0
79	N 5720 WEST ST	10681	10769	150	21	Aligator	Reconstruct	\$43,023.07	34	194.7
80	N 5730 WEST ST	10901	10999	142	80	Long/Trans	Slurry Seal	\$2,224.46	32	657.3
81	N 5730 WEST ST	11001	11199	135	78	Long/Trans	Slurry Seal	\$4,737.07	34	1321.4
82	N 5740 WEST ST	9931	9949	202	80	Long/Trans	Slurry Seal	\$562.31	34	157.1
83	N 5740 WEST ST	9951	9969	202	80	Long/Trans	Slurry Seal	\$863.97	34	241.3
84	N 5750 WEST ST	10101	10199	204	78	Patching	Slurry Seal	\$1,657.54	34	446.4
85	N 5750 WEST ST	10201	10213	204	78	Patching	Slurry Seal	\$583.29	34	157.1
86	N 5750 WEST ST	10761	10799	150	21	Aligator	Reconstruct	\$37,522.22	34	169.8
87	N 5750 WEST ST	10801	10899	142	80	Long/Trans	Slurry Seal	\$2,309.51	32	682.4
88	N 5750 WEST ST	10801	10899	150	21	Aligator	Reconstruct	\$35,716.12	34	161.6
89	N 5800 WEST ST	9851	9899	194	90	Weathering	Slurry Seal	\$809.66	34	238.1
90	N 5800 WEST ST	9941	9969	202	80	Long/Trans	Slurry Seal	\$1,077.61	34	301.0

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
91	N 5800 WEST ST	9971	10039	202	80	Long/Trans	Slurry Seal	\$1,577.04	34	440.5
92	N 5800 WEST ST	10041	10099	202	80	Long/Trans	Slurry Seal	\$1,438.51	34	401.8
93	N 5800 WEST ST	10101	10209	204	78	Patching	Slurry Seal	\$2,227.37	34	599.8
94	N 5800 WEST ST	10211	10239	204	78	Patching	Slurry Seal	\$583.29	34	157.1
95	N 5800 WEST ST	10805	10819	141	86	Long/Trans	Slurry Seal	\$562.16	34	157.1
96	N 5800 WEST ST	10821	10899	141	86	Long/Trans	Slurry Seal	\$1,599.09	34	446.8
97	N 5800 WEST ST	10901	10949	141	86	Long/Trans	Slurry Seal	\$1,413.57	34	395.0
98	N 5800 WEST ST	10951	10989	141	86	Long/Trans	Slurry Seal	\$562.16	34	157.1
99	N 5870 WEST ST	10801	10879	140	66	Long/Trans	Mill & Overlay	\$59,216.23	34	484.2
100	N 5870 WEST ST	10801	10879	151	66	Long/Trans	Chip Seal	\$11,020.80	34	180.2
101	N 5870 WEST ST	10881	10899	140	34	Alligator	Mill & Overlay	\$18,959.86	34	155.0
102	N 5870 WEST ST	10901	10923	140	34	Alligator	Mill & Overlay	\$18,659.34	34	152.6
103	N 5870 WEST ST	10925	10999	140	50	Alligator	Mill & Overlay	\$65,566.37	34	536.1
104	N 5900 WEST ST	10101	10191	205	50	Weathering	Mill & Overlay	\$66,017.83	34	647.2
105	N 5900 WEST ST	10551	10569	153	78	Long/Trans	Slurry Seal	\$1,380.07	34	372.9
106	N 5920 WEST ST	9701	9799	192	68	Long/Trans	Chip Seal	\$19,047.60	34	557.3
107	N 5920 WEST ST	9801	9819	192	68	Long/Trans	Chip Seal	\$4,528.51	34	132.5
108	N 5920 WEST ST	10761	10769	151	66	Long/Trans	Chip Seal	\$9,606.34	34	157.1
109	N 5920 WEST ST	10771	10799	151	66	Long/Trans	Chip Seal	\$6,362.02	34	104.0
110	N 5920 WEST ST	10801	10899	140	34	Long/Trans	Mill & Overlay	\$59,221.92	34	484.2
111	N 5920 WEST ST	10801	10899	151	66	Long/Trans	Chip Seal	\$11,068.83	34	181.0
112	N 5920 WEST ST	10921	10999	140	34	Alligator	Mill & Overlay	\$65,477.59	34	535.4
113	N 5950 WEST ST	10101	10199	206	62	Alligator	Chip Seal	\$31,984.70	34	655.4
114	N 6000 WEST ST	9601	9639	191	35	Alligator	Reconstruct	\$68,181.62	34	308.5
115	N 6000 WEST ST	9641	9683	191	35	Alligator	Reconstruct	\$34,714.03	34	157.1
116	N 6000 WEST ST	9701	9739	27	18	Bumps	Reconstruct	\$67,458.61	44	235.9
117	N 6000 WEST ST	9741	9799	27	18	Bumps	Reconstruct	\$111,199.60	44	388.8
118	N 6000 WEST ST	9801	9849	26	52	Alligator	Chip Seal	\$10,090.61	44	397.8
119	N 6000 WEST ST	9851	9959	26	52	Alligator	Chip Seal	\$9,638.24	44	380.0
120	N 6000 WEST ST	9851	9959	26	52	Alligator	Chip Seal	\$5,539.99	30	320.4
121	N 6000 WEST ST	9961	10049	26	52	Alligator	Chip Seal	\$3,877.00	24	280.2
122	N 6000 WEST ST	9961	10049	26	52	Alligator	Chip Seal	\$5,331.01	34	272.0
123	N 6000 WEST ST	10051	10089	26	52	Alligator	Chip Seal	\$4,573.50	24	330.6
124	N 6000 WEST ST	10091	10099	25	16	Pothole	Reconstruct	\$16,891.88	24	108.3
125	N 6000 WEST ST	10101	10109	25	16	Pothole	Reconstruct	\$16,891.16	24	108.3
126	N 6000 WEST ST	10111	10269	25	16	Pothole	Reconstruct	\$152,489.70	34	690.0
127	N 6000 WEST ST	10111	10269	25	16	Pothole	Reconstruct	\$52,556.78	24	336.9
128	N 6000 WEST ST	10271	10345	25	16	Pothole	Reconstruct	\$61,545.23	24	394.5
129	N 6000 WEST ST	10347	10399	25	16	Pothole	Reconstruct	\$62,440.70	24	400.3
130	N 6000 WEST ST	10401	10549	24	38	Alligator	Mill & Overlay	\$91,422.61	26	984.3
131	N 6000 WEST ST	10551	10619	24	38	Alligator	Mill & Overlay	\$71,684.30	44	456.0
132	N 6000 WEST ST	10621	10679	24	38	Alligator	Mill & Overlay	\$66,002.32	44	419.9
133	N 6000 WEST ST	10681	10689	23	32	Alligator	Overlay	\$32,413.32	44	291.1
134	N 6000 WEST ST	10691	10799	23	32	Alligator	Overlay	\$43,584.13	44	391.4
135	N 6000 WEST ST	10801	10929	23	32	Alligator	Overlay	\$103,664.07	44	930.9

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
136	N 6000 WEST ST	10931	10999	23	32	Alligator	Overlay	\$54,533.44	41	525.6
137	N 6000 WEST ST	11001	11139	22	44	Alligator	Overlay	\$74,137.78	38	911.0
138	N 6000 WEST ST	11141	11249	22	44	Alligator	Overlay	\$24,819.94	38	305.0
139	N 6000 WEST ST	11141	11249	22	44	Alligator	Overlay	\$6,859.32	27	118.6
140	N 6000 WEST ST	11251	11359	22	44	Alligator	Overlay	\$51,460.14	27	890.0
141	N 6000 WEST ST	11251	11359	22	44	Alligator	Overlay	\$19,369.64	44	205.6
142	N 6000 WEST ST	11361	11429	21	48	Alligator	Overlay	\$41,603.35	44	422.0
143	N 6000 WEST ST	11431	11499	21	48	Alligator	Overlay	\$41,281.99	44	418.8
144	N 6000 WEST ST	11501	11579	21	48	Alligator	Overlay	\$41,425.18	34	543.8
145	N 6000 WEST ST	11581	11699	21	48	Alligator	Overlay	\$55,171.49	34	724.3
146	N 6000 WEST ST	11701	11799	21	48	Alligator	Overlay	\$57,985.12	34	761.2
147	N 6020 WEST ST	9801	9829	187	78	Weathering	Slurry Seal	\$6,045.69	34	219.1
148	N 6020 WEST ST	9831	9843	187	78	Weathering	Slurry Seal	\$4,334.10	34	157.1
149	N 6040 WEST ST	9861	9869	187	78	Weathering	Slurry Seal	\$3,855.78	34	139.7
150	N 6040 WEST ST	9871	9889	187	78	Weathering	Slurry Seal	\$4,329.25	34	156.9
151	N 6050 WEST ST	9601	9699	27	18	Bumps	Reconstruct	\$200,733.86	44	701.9
152	N 6080 WEST ST	9801	9829	187	78	Weathering	Slurry Seal	\$7,005.91	34	253.9
153	N 6080 WEST ST	9831	9849	187	78	Weathering	Slurry Seal	\$4,334.08	34	157.1
154	N 6100 WEST ST	9651	9659	189	49	Alligator	Overlay	\$12,784.09	34	157.1
155	N 6100 WEST ST	9661	9679	189	49	Alligator	Overlay	\$12,014.74	34	147.6
156	N 6100 WEST ST	9681	9739	188	60	Patching	Chip Seal	\$5,787.22	34	204.8
157	N 6100 WEST ST	9681	9739	189	49	Alligator	Overlay	\$14,824.40	34	182.1
158	N 6100 WEST ST	9741	9753	188	60	Patching	Chip Seal	\$6,462.96	34	228.7
159	N 6100 WEST ST	9741	9753	187	78	Weathering	Slurry Seal	\$4,315.37	34	156.4
160	N 6110 WEST ST	9861	9869	187	78	Weathering	Slurry Seal	\$3,221.41	34	116.8
161	N 6110 WEST ST	9871	9889	187	78	Weathering	Slurry Seal	\$4,334.13	34	157.1
162	N 6120 WEST ST	10731	10759	139	42	Alligator	Mill & Overlay	\$30,207.79	34	251.0
163	N 6130 WEST ST	9801	9829	187	78	Weathering	Slurry Seal	\$7,121.15	34	258.1
164	N 6130 WEST ST	9831	9849	187	78	Weathering	Slurry Seal	\$4,334.10	34	157.1
165	N 6150 WEST ST	9601	9679	189	49	Alligator	Overlay	\$41,120.87	34	505.2
166	N 6150 WEST ST	10511	10549	155	48	Pothole	Overlay	\$30,747.42	34	505.2
167	N 6150 WEST ST	10831	10929	139	42	Alligator	Mill & Overlay	\$70,537.99	34	317.4
168	N 6150 WEST ST	11761	11799	110	54	Patching	Mill & Overlay	\$42,510.52	34	586.1
169	N 6150 WEST ST	11801	11869	108	34	Depressions	Reconstruct	\$97,904.86	34	270.1
170	N 6160 WEST ST	9961	10003	193	80	Weathering	Slurry Seal	\$423.81	34	124.6
171	N 6160 WEST ST	10005	10049	174	58	Long/Trans	Overlay	\$30,380.04	34	286.2
172	N 6160 WEST ST	10005	10049	193	80	Weathering	Slurry Seal	\$524.44	34	154.1
173	N 6180 WEST ST	9801	9859	187	78	Weathering	Slurry Seal	\$12,712.42	34	460.7
174	N 6180 WEST ST	9861	9959	187	78	Weathering	Slurry Seal	\$13,126.85	34	475.7
175	N 6190 WEST ST	11821	11829	108	34	Depressions	Reconstruct	\$34,713.78	34	157.1
176	N 6190 WEST ST	11831	11839	108	34	Depressions	Reconstruct	\$11,948.20	34	54.1
177	N 6200 WEST ST	10761	10829	139	42	Alligator	Mill & Overlay	\$51,623.42	34	429.0
178	N 6220 WEST ST	9681	9725	189	49	Alligator	Overlay	\$23,656.05	34	290.7
179	N 6250 WEST ST	9861	9863	186	78	Long/Trans	Slurry Seal	\$513.81	34	147.2
180	N 6250 WEST ST	9865	9899	186	78	Long/Trans	Slurry Seal	\$548.40	34	157.1

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
181	N 6250 WEST ST	10501	10569	157	70	Long/Trans	Chip Seal	\$18,438.01	34	445.1
182	N 6250 WEST ST	10501	10569	158	42	Patching	Mill & Overlay	\$35,345.09	34	196.1
183	N 6250 WEST ST	10571	10679	157	70	Long/Trans	Chip Seal	\$35,606.67	34	859.6
184	N 6260 WEST ST	11821	11829	108	34	Depressions	Reconstruct	\$34,713.37	34	157.1
185	N 6260 WEST ST	11831	11839	108	34	Depressions	Reconstruct	\$17,654.93	34	79.9
186	N 6300 WEST ST	10401	10499	158	42	Patching	Mill & Overlay	\$106,637.94	34	591.6
187	N 6320 WEST ST	9861	9863	186	78	Long/Trans	Slurry Seal	\$500.61	34	143.4
188	N 6320 WEST ST	9865	9899	186	78	Long/Trans	Slurry Seal	\$548.42	34	157.1
189	N 6330 WEST ST	10891	10699	138	86	Patching	Slurry Seal	\$1,323.44	34	384.7
190	N 6340 WEST ST	10665	10699	156	86	Weathering	Slurry Seal	\$479.50	34	139.1
191	N 6340 WEST ST	10701	10713	156	86	Weathering	Slurry Seal	\$541.48	34	157.1
192	N 6400 WEST ST	10351	10399	232	78	Weathering	Slurry Seal	\$1,584.44	36	430.0
193	N 6400 WEST ST	10351	10399	231	100	None	Do Nothing	\$0.00	36	423.0
194	N 6400 WEST ST	10401	10499	29	24	Aligator	Reconstruct	\$188,900.61	43	675.9
195	N 6400 WEST ST	10501	10569	29	24	Aligator	Reconstruct	\$50,118.13	29	265.9
196	N 6400 WEST ST	10501	10569	29	24	Aligator	Reconstruct	\$55,899.89	43	200.0
197	N 6400 WEST ST	10571	10629	29	24	Aligator	Reconstruct	\$72,658.37	29	385.5
198	N 6400 WEST ST	10631	10669	28	20	Aligator	Reconstruct	\$46,686.75	24	299.3
199	N 6400 WEST ST	10671	10759	28	20	Aligator	Reconstruct	\$54,899.95	29	291.2
200	N 6400 WEST ST	10671	10759	28	20	Aligator	Reconstruct	\$41,339.92	24	265.0
201	N 6400 WEST ST	10761	10829	28	20	Aligator	Reconstruct	\$102,596.60	34	464.2
202	N 6400 WEST ST	10831	10889	28	20	Aligator	Reconstruct	\$90,270.44	34	408.5
203	N 6400 WEST ST	10891	10899	28	20	Aligator	Reconstruct	\$47,385.05	44	165.7
204	N 6400 WEST ST	10901	10999	28	20	Aligator	Reconstruct	\$160,440.04	44	561.0
205	N 6530 WEST ST	9601	9809	184	78	Block	Slurry Seal	\$7,349.43	34	1433.6
206	N 6530 WEST ST	10301	10379	169	49	Aligator	Overlay	\$44,835.40	34	445.2
207	N 6560 WEST ST	9445	9459	182	50	Weathering	Overlay	\$24,140.67	34	157.4
208	N 6560 WEST ST	9461	9499	182	50	Weathering	Overlay	\$26,223.61	34	171.0
209	N 6560 WEST ST	9501	9599	182	50	Weathering	Overlay	\$107,821.18	34	703.2
210	N 6570 WEST ST	10401	10439	163	78	Depressions	Do Nothing	\$0.00	34	308.2
211	N 6570 WEST ST	10441	10479	163	78	Depressions	Do Nothing	\$0.00	34	157.1
212	N 6580 WEST ST	10031	10119	170	74	Aligator	Chip Seal	\$14,456.82	34	612.2
213	N 6580 WEST ST	10121	10199	170	74	Aligator	Chip Seal	\$12,228.36	34	517.8
214	N 6580 WEST ST	10201	10249	170	74	Aligator	Chip Seal	\$12,072.41	34	511.2
215	N 6580 WEST ST	10251	10299	169	49	Aligator	Overlay	\$26,019.33	34	258.3
216	N 6580 WEST ST	10301	10379	169	49	Aligator	Overlay	\$42,955.38	34	426.5
217	N 6580 WEST ST	10381	10399	169	49	Aligator	Overlay	\$17,957.62	34	178.3
218	N 6610 WEST ST	9951	10029	176	70	Pothole	Mill & Overlay	\$48,873.45	34	376.7
219	N 6610 WEST ST	9951	10029	170	74	Aligator	Chip Seal	\$4,277.84	34	181.1
220	N 6620 WEST ST	9501	9599	180	68	Weathering	Chip Seal	\$10,231.22	34	663.5
221	N 6630 WEST ST	9721	9769	179	48	Depressions	Overlay	\$26,891.49	34	188.1
222	N 6630 WEST ST	9721	9769	177	75	Block	Chip Seal	\$1,259.74	34	179.7
223	N 6630 WEST ST	9771	9809	177	75	Block	Chip Seal	\$1,652.40	34	235.7
224	N 6630 WEST ST	9811	9849	177	75	Block	Chip Seal	\$1,784.47	34	254.6
225	N 6630 WEST ST	9851	9949	176	70	Pothole	Mill & Overlay	\$59,281.85	34	456.9

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
226	N 6630 WEST ST	9851	9949	177	75	Block	Chip Seal	\$1,293.84	34	184.6
227	N 6630 WEST ST	10251	10299	169	49	Alligator	Overlay	\$36,573.25	34	363.1
228	N 6630 WEST ST	10301	10329	169	49	Alligator	Overlay	\$15,820.62	34	157.1
229	N 6670 WEST ST	9601	9679	179	48	Depressions	Overlay	\$59,434.48	34	415.7
230	N 6670 WEST ST	9681	9719	179	48	Depressions	Overlay	\$57,372.91	34	401.3
231	N 6670 WEST ST	9951	9969	176	70	Pothole	Mill & Overlay	\$30,025.19	34	231.4
232	N 6670 WEST ST	9971	9989	176	70	Pothole	Mill & Overlay	\$20,385.02	34	157.1
233	N 6680 WEST ST	10257	10379	169	49	Alligator	Overlay	\$71,091.92	34	705.9
234	N 6690 WEST ST	9895	9899	176	70	Pothole	Mill & Overlay	\$20,379.99	34	157.1
235	N 6690 WEST ST	9901	9913	176	70	Pothole	Mill & Overlay	\$6,826.23	34	52.6
236	N 6690 WEST ST	10051	10119	170	74	Alligator	Chip Seal	\$13,660.70	34	578.5
237	N 6750 WEST ST	10401	10429	161	46	Alligator	Chip Seal	\$10,132.10	34	213.8
238	N 6750 WEST ST	10431	10469	161	46	Alligator	Chip Seal	\$15,543.26	34	328.0
239	N 6790 WEST ST	10441	10459	161	46	Alligator	Chip Seal	\$8,366.76	34	176.6
240	N 6790 WEST ST	10461	10469	161	46	Alligator	Chip Seal	\$7,443.45	34	157.1
241	N 6800 WEST ST	9401	9499	32	20	Alligator	Reconstruct	\$100,209.72	26	593.0
242	N 6800 WEST ST	9501	9569	32	20	Alligator	Reconstruct	\$59,698.96	26	353.2
243	N 6800 WEST ST	9571	9599	32	20	Alligator	Reconstruct	\$57,133.53	44	199.8
244	N 6800 WEST ST	9571	9599	32	20	Alligator	Reconstruct	\$31,433.94	26	186.0
245	N 6800 WEST ST	9601	9769	32	22	Alligator	Reconstruct	\$101,867.80	24	653.0
246	N 6800 WEST ST	9601	9769	32	60	Long/Trans	Overlay	\$13,995.44	24	191.8
247	N 6800 WEST ST	9601	9769	32	22	Alligator	Reconstruct	\$115,114.77	55	322.0
248	N 6800 WEST ST	9771	9799	233	60	Long/Trans	Overlay	\$27,665.98	47	193.6
249	N 6800 WEST ST	9771	9799	233	60	Long/Trans	Overlay	\$11,018.75	24	151.0
250	N 6800 WEST ST	9801	9849	233	60	Long/Trans	Overlay	\$21,806.72	47	152.6
251	N 6800 WEST ST	9851	9899	233	60	Long/Trans	Overlay	\$53,431.09	47	373.9
252	N 6800 WEST ST	9901	9973	31	53	Alligator	Overlay	\$65,966.15	47	451.7
253	N 6800 WEST ST	9975	10125	31	53	Alligator	Overlay	\$80,297.64	38	680.0
254	N 6800 WEST ST	9975	10125	31	53	Alligator	Overlay	\$21,469.67	47	147.0
255	N 6800 WEST ST	9975	10125	31	53	Alligator	Overlay	\$21,703.18	52	134.3
256	N 6800 WEST ST	10127	10149	31	53	Alligator	Overlay	\$23,321.71	52	144.3
257	N 6800 WEST ST	10151	10205	30	58	Long/Trans	Overlay	\$64,227.26	52	425.8
258	N 6800 WEST ST	10207	10249	30	58	Long/Trans	Overlay	\$46,443.89	52	307.9
259	N 6800 WEST ST	10251	10299	30	58	Long/Trans	Overlay	\$39,826.34	52	264.0
260	N 6800 WEST ST	10301	10399	30	58	Long/Trans	Overlay	\$108,256.35	52	717.6
261	N 6890 WEST ST	10151	10205	166	68	Patching	Chip Seal	\$4,687.69	34	418.3
262	N 6900 WEST ST	10301	10399	164	80	Long/Trans	Slurry Seal	\$2,574.44	34	719.7
263	N 6960 WEST ST	10121	10149	166	68	Patching	Chip Seal	\$3,179.90	34	283.7
264	N 6960 WEST ST	10151	10299	166	68	Patching	Chip Seal	\$7,899.52	34	704.9
265	N 6960 WEST ST	10151	10299	164	80	Long/Trans	Slurry Seal	\$919.08	34	256.9
266	N 6960 WEST ST	10301	10369	164	80	Long/Trans	Slurry Seal	\$1,646.78	34	460.4
267	N 6960 WEST ST	10371	10389	164	80	Long/Trans	Slurry Seal	\$561.86	34	157.1
268	N AINSLEY WAY	10431	10499	161	46	Alligator	Chip Seal	\$36,427.27	34	768.7
269	N AINSLEY WAY	10501	10509	161	46	Alligator	Chip Seal	\$7,156.44	34	151.0
270	N ALPINE HWY	9621	9699	20	59	Block	Chip Seal	\$37,570.52	58	695.8

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
271	N ALPINE HWY	9701	9759	20	59	Block	Chip Seal	\$11,794.23	50	253.4
272	N ALPINE HWY	9701	9759	20	59	Block	Chip Seal	\$5,399.89	58	100.0
273	N ALPINE HWY	9761	9799	20	59	Block	Chip Seal	\$8,398.57	50	180.4
274	N ALPINE HWY	9801	9829	20	59	Block	Chip Seal	\$13,003.98	64	218.2
275	N ALPINE HWY	9831	9909	20	59	Block	Chip Seal	\$15,492.11	64	260.0
276	N ALPINE HWY	9831	9909	20	59	Block	Chip Seal	\$10,499.43	50	225.5
277	N ALPINE HWY	9911	9949	20	59	Block	Chip Seal	\$17,751.34	64	297.9
278	N ALPINE HWY	9951	9969	19	43	Alligator	Overlay	\$18,766.47	58	119.2
279	N ALPINE HWY	9971	10029	19	43	Alligator	Overlay	\$70,940.08	58	450.5
280	N ALPINE HWY	10031	10129	19	43	Alligator	Overlay	\$92,800.75	50	683.6
281	N ALPINE HWY	10131	10179	19	43	Alligator	Overlay	\$63,390.22	70	333.5
282	N ALPINE HWY	10181	10229	19	43	Alligator	Overlay	\$74,010.31	70	389.4
283	N ALPINE HWY	10231	10399	19	43	Alligator	Overlay	\$93,289.32	60	572.7
284	N ALPINE HWY	10231	10399	19	43	Alligator	Overlay	\$90,273.57	70	475.0
285	N ALPINE HWY	10401	10479	18	48	Alligator	Overlay	\$95,603.58	68	532.0
286	N ALPINE HWY	10481	10539	18	48	Alligator	Overlay	\$81,716.55	68	454.7
287	N ALPINE HWY	10541	10609	18	48	Alligator	Overlay	\$92,317.85	68	513.7
288	N ALPINE HWY	10611	10699	18	48	Alligator	Overlay	\$102,275.86	61	634.4
289	N ALPINE HWY	10701	10899	17	50	Alligator	Overlay	\$200,635.45	68	1215.2
290	N ALPINE HWY	10901	10999	17	50	Alligator	Overlay	\$108,352.79	64	697.3
291	N ALPINE HWY	11001	11099	16	45	Alligator	Overlay	\$107,225.39	68	616.4
292	N ALPINE HWY	11101	11129	16	45	Alligator	Overlay	\$27,514.56	68	158.2
293	N ALPINE HWY	11131	11199	16	45	Alligator	Overlay	\$88,254.66	64	539.0
294	N ALPINE HWY	11201	11419	16	45	Alligator	Overlay	\$119,027.29	58	802.2
295	N ALPINE HWY	11201	11419	16	45	Alligator	Overlay	\$74,700.75	40	730.0
296	N ANDREW DR	11241	11289	120	48	Block	Overlay	\$59,088.59	34	559.8
297	N ANDREW DR	11291	11349	120	48	Block	Overlay	\$40,168.99	34	380.5
298	N ANGELS GATE	12471	12649	100	86	Weathering	Slurry Seal	\$3,702.15	34	1085.8
299	N ANGELS GATE	12651	12699	100	86	Weathering	Slurry Seal	\$1,798.94	34	527.6
300	N APOLLO WAY	11861	11879	108	34	Depressions	Reconstruct	\$35,617.18	34	161.2
301	N APOLLO WAY	11881	11949	108	34	Depressions	Reconstruct	\$102,848.82	34	465.4
302	N APOLLO WAY	11951	11999	107	50	Weathering	Overlay	\$35,609.49	34	261.0
303	N ASHBY LN	9601	9779	195	70	Long/Trans	Chip Seal	\$7,995.05	24	1371.7
304	N ASHBY LN	9781	9809	195	70	Long/Trans	Chip Seal	\$915.53	24	157.1
305	N ASPEN HOLLOW CIR	9401	9439	181	90	Weathering	Slurry Seal	\$688.90	34	201.6
306	N ASPEN HOLLOW CIR	9441	9459	181	90	Weathering	Slurry Seal	\$536.83	34	157.1
307	N ATHENA DR	11801	11829	106	70	Long/Trans	Chip Seal	\$11,853.88	34	183.5
308	N ATHENA DR	11831	11859	106	70	Long/Trans	Chip Seal	\$15,119.54	34	234.1
309	N ATHENA DR	11861	11999	106	70	Long/Trans	Chip Seal	\$57,061.87	34	883.4
310	N ATLAS DR	11835	11959	109	68	Long/Trans	Chip Seal	\$71,727.26	34	1089.9
311	N ATLAS DR	11961	11999	109	68	Long/Trans	Chip Seal	\$15,684.88	34	238.3
312	N AVERY AVE	10501	10569	159	78	Weathering	Slurry Seal	\$1,343.84	34	394.1
313	N AVERY AVE	10571	10599	159	78	Weathering	Slurry Seal	\$534.10	34	156.6
314	N AVERY AVE	10661	10689	159	78	Weathering	Slurry Seal	\$885.44	34	259.7
315	N AVONMORE CT	11141	11179	136	78	Weathering	Slurry Seal	\$930.56	42	214.6

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
316	N AVONMORE CT	11181	11183	136	78	Weathering	Slurry Seal	\$681.06	42	157.1
317	N AVONMORE DR	11001	11089	136	78	Weathering	Slurry Seal	\$2,566.00	42	591.8
318	N AVONMORE DR	11091	11139	136	78	Weathering	Slurry Seal	\$1,539.14	42	355.0
319	N BEACON HILL BLVD	11801	11849	42	65	Long/Trans	Chip Seal	\$27,499.45	34	307.7
320	N BEACON HILL BLVD	11851	11949	42	65	Long/Trans	Chip Seal	\$57,656.85	34	645.2
321	N BEACON HILL BLVD	11951	11989	42	65	Long/Trans	Chip Seal	\$30,284.97	34	338.9
322	N BEACON HILL BLVD	11991	12059	42	65	Long/Trans	Chip Seal	\$24,384.76	34	272.9
323	N BEACON HILL BLVD	12061	12219	43	66	Long/Trans	Chip Seal	\$64,367.63	34	1200.5
324	N BRITANY CIR	11245	11249	118	90	Weathering	Slurry Seal	\$373.53	34	108.9
325	N BRITANY CIR	11251	11253	118	90	Weathering	Slurry Seal	\$538.94	34	157.1
326	N BROADLEAF HOLLOW LN	11431	11509	112	80	Weathering	Slurry Seal	\$1,778.69	34	515.4
327	N BROADLEAF HOLLOW LN	11511	11599	112	80	Weathering	Slurry Seal	\$1,905.05	34	552.1
328	N BULL RIVER CIR	11501	11519	115	62	Depressions	Slurry Seal	\$3,872.04	34	125.5
329	N BULL RIVER CIR	11521	11529	115	62	Depressions	Slurry Seal	\$4,844.67	34	157.1
330	N CALAIS CIR	11231	11289	118	90	Weathering	Slurry Seal	\$1,744.31	34	508.4
331	N CALAIS CIR	11291	11299	118	90	Weathering	Slurry Seal	\$538.94	34	157.1
332	N CAMBRIDGE CT	9835	9849	201	90	Patching	Slurry Seal	\$486.63	30	157.1
333	N CAMBRIDGE CT	9851	9889	201	90	Patching	Slurry Seal	\$994.51	30	321.0
334	N CANTERBURY DR	0	0	159	78	Weathering	Slurry Seal	\$1,585.01	34	464.8
335	N CANTERBURY DR	0	0	159	78	Weathering	Slurry Seal	\$1,513.03	34	443.7
336	N CANTERBURY DR	0	0	160	49	Weathering	Slurry Seal	\$10,001.98	34	87.7
337	N CANTERBURY DR	10401	10429	161	46	Aligator	Chip Seal	\$9,795.78	34	206.7
338	N CANTERBURY DR	10431	10509	161	46	Aligator	Chip Seal	\$43,010.03	34	907.7
339	N CANTERBURY DR	10511	10529	161	46	Aligator	Chip Seal	\$12,347.43	34	260.6
340	N CANTERBURY DR	10531	10547	161	46	Aligator	Chip Seal	\$12,982.09	34	274.0
341	N CANTERBURY DR	10551	10611	160	49	Weathering	Overlay	\$29,333.61	34	257.1
342	N CANTERBURY DR	10613	10615	159	78	Weathering	Slurry Seal	\$199.18	34	58.4
343	N CANTERBURY DR	10625	10653	160	49	Weathering	Overlay	\$33,020.82	34	289.4
344	N CANTERBURY LN	6675	6699	160	49	Weathering	Overlay	\$57,459.53	34	503.5
345	N CANTERBURY LN	10401	10429	160	49	Weathering	Overlay	\$22,928.97	34	200.9
346	N CANTERBURY LN	10431	10563	160	49	Weathering	Overlay	\$85,042.14	34	745.2
347	N CANTERBURY PARK CIR	9701	9799	192	68	Long/Trans	Chip Seal	\$16,130.05	34	472.0
348	N CANTERBURY PL	10431	10499	161	46	Aligator	Chip Seal	\$28,892.35	34	609.7
349	N CANTERBURY PL	10501	10539	160	49	Weathering	Overlay	\$42,014.48	34	368.2
350	N CANTERBURY PL	10541	10565	160	49	Weathering	Overlay	\$34,580.25	34	303.0
351	N CANTERBURY WAY	10521	10599	160	49	Weathering	Overlay	\$56,809.23	34	497.8
352	N CANYON LINKS VISTA	10835	10849	220	58	Block	Overlay	\$10,681.41	34	157.1
353	N CANYON LINKS VISTA	10851	10969	220	58	Block	Overlay	\$30,839.05	34	453.5
354	N CANYON VIEW DR	10741	10799	220	58	Block	Overlay	\$21,196.31	34	311.7
355	N CANYON VIEW DR	10801	10885	220	58	Block	Overlay	\$19,297.85	34	283.8
356	N CASTLE PINE DR	10551	10619	216	80	Depressions	Do Nothing	\$0.00	34	603.0
357	N CASTLE PINE DR	10621	10683	216	80	Depressions	Do Nothing	\$0.00	34	239.1
358	N CASTLE PINE WAY	10551	10619	216	80	Depressions	Do Nothing	\$0.00	34	660.5
359	N CHAMBERRY CT	12001	12029	106	70	Long/Trans	Chip Seal	\$17,904.69	34	277.2
360	N CHAMBERRY CT	12031	12049	106	70	Long/Trans	Chip Seal	\$10,146.30	34	157.1

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
361	N CHERRY LN	10401	10459	212	70	Long/Trans	Chip Seal	\$5,644.15	34	430.1
362	N CHERRY LN	10461	10479	212	70	Long/Trans	Chip Seal	\$2,061.49	34	157.1
363	N COTTONWOOD MEADOWS	10375	10389	165	70	Pothole	Chip Seal	\$1,995.48	34	157.1
364	N COTTONWOOD MEADOWS	10391	10399	165	70	Pothole	Chip Seal	\$1,947.66	34	153.3
365	N COUNTRY CLUB DR	10661	10699	215	73	Block	Chip Seal	\$4,062.12	37	150.2
366	N COVENTRY CT	9861	9879	201	90	Patching	Slurry Seal	\$486.63	30	157.1
367	N COVENTRY CT	9881	9915	201	90	Patching	Slurry Seal	\$856.52	30	276.5
368	N CRESTVIEW DR	10681	10799	145	86	Weathering	Slurry Seal	\$1,574.66	34	452.2
369	N CYPRIUS DR	11801	11833	108	34	Depressions	Reconstruct	\$48,885.05	34	221.2
370	N CYPRIUS DR	11835	11869	108	34	Depressions	Reconstruct	\$49,144.90	34	222.4
371	N CYPRIUS DR	11871	11889	108	34	Depressions	Reconstruct	\$32,080.00	34	145.2
372	N CYPRIUS DR	11891	11899	108	34	Depressions	Reconstruct	\$36,589.29	34	165.6
373	N CYPRIUS DR	11901	11939	108	34	Depressions	Reconstruct	\$61,206.52	34	277.0
374	N CYPRIUS DR	11941	11949	108	34	Depressions	Reconstruct	\$37,163.56	34	168.2
375	N CYPRIUS DR	11951	11989	108	34	Depressions	Reconstruct	\$31,646.82	34	143.2
376	N CYPRIUS DR	11991	12099	107	50	Weathering	Overlay	\$118,050.51	34	865.3
377	N DEER HOLLOW WAY	10551	10599	159	78	Weathering	Slurry Seal	\$525.95	34	154.3
378	N DIAMOND LN	9601	9679	189	49	Alligator	Overlay	\$40,998.07	34	503.7
379	N EAGLEVIEW CIR	9601	9669	190	90	Weathering	Slurry Seal	\$1,974.29	34	574.0
380	N EAGLEVIEW CIR	9671	9703	190	90	Weathering	Slurry Seal	\$540.23	34	157.1
381	N EAST CRIMSON CT	9871	9899	194	90	Weathering	Slurry Seal	\$747.03	34	219.7
382	N EAST CRIMSON CT	9901	9903	194	90	Weathering	Slurry Seal	\$534.06	34	157.1
383	N EAST JERLING DR	10621	10659	215	73	Block	Chip Seal	\$12,805.56	34	515.2
384	N EAST JERLING DR	10661	10699	215	73	Block	Chip Seal	\$12,177.91	34	489.9
385	N EAST PANORAMA DR	10921	10947	220	58	Block	Overlay	\$14,054.51	34	206.7
386	N ENGLISH MEADOWS CT	9751	9789	196	70	Long/Trans	Chip Seal	\$5,733.80	34	393.2
387	N ENGLISH MEADOWS CT	9791	9819	196	70	Long/Trans	Chip Seal	\$2,290.65	34	157.1
388	N ENGLISH MEADOWS DR	9601	9749	196	70	Long/Trans	Chip Seal	\$15,788.92	34	1082.7
389	N FLOWERING PLUM LN	11481	11549	113	78	Weathering	Slurry Seal	\$2,471.91	34	704.3
390	N GRANITE CIR	11505	11509	115	62	Depressions	Slurry Seal	\$10,299.78	34	334.0
391	N GRANITE CIR	11511	11539	115	62	Depressions	Slurry Seal	\$4,844.65	34	157.1
392	N GRANITE FLATS RD	0	0	110	54	Patching	Mill & Overlay	\$10,295.03	34	65.4
393	N GRANITE FLATS RD	0	0	110	54	Patching	Mill & Overlay	\$16,505.25	34	104.9
394	N GRANITE FLATS RD	0	0	110	54	Patching	Mill & Overlay	\$8,397.04	34	53.4
395	N GRANITE FLATS RD	11501	11599	115	62	Depressions	Slurry Seal	\$19,871.71	34	644.3
396	N GRANITE FLATS RD	11601	11629	110	54	Patching	Mill & Overlay	\$33,423.38	34	212.4
397	N GRANITE FLATS RD	11601	11629	115	62	Depressions	Slurry Seal	\$5,635.62	34	182.7
398	N GRANITE FLATS RD	11691	11689	110	54	Patching	Mill & Overlay	\$55,750.66	34	354.3
399	N GRANITE FLATS RD	11691	11759	110	54	Patching	Mill & Overlay	\$70,570.68	34	448.5
400	N GRENABLE	12001	12099	106	70	Long/Trans	Chip Seal	\$37,526.99	34	581.0
401	N HANCOCK PL	9601	9643	185	40	Bumps	Mill & Overlay	\$14,988.03	30	166.5
402	N HANCOCK PL	9645	9649	185	40	Bumps	Mill & Overlay	\$14,132.81	30	157.0
403	N HARVEST MOON LN	11841	11959	105	80	Weathering	Slurry Seal	\$2,243.66	34	656.7
404	N HAYMAKER LN	10461	10499	148	90	Weathering	Slurry Seal	\$1,395.10	34	410.3
405	N HIDDEN DR	9849	9909	200	90	Long/Trans	Slurry Seal	\$1,648.77	34	459.3

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
406	N HIDDEN POND DR	10151	10249	171	32	Weathering	Reconstruct	\$171,114.05	34	774.3
407	N HIGHLAND BLVD	0	0	33	61	Long/Trans	Chip Seal	\$3,449.00	26	800.4
408	N HIGHLAND BLVD	0	0	33	61	Long/Trans	Chip Seal	\$3,420.66	32	645.0
409	N HIGHLAND BLVD	0	0	34	68	Long/Trans	Chip Seal	\$1,405.15	24	370.2
410	N HIGHLAND BLVD	0	0	34	68	Long/Trans	Chip Seal	\$4,828.43	24	1272.2
411	N HIGHLAND BLVD	0	0	35	32	Alligator	Mill & Overlay	\$43,694.67	25	380.6
412	N HIGHLAND BLVD	0	0	35	32	Alligator	Mill & Overlay	\$120,918.78	25	1053.4
413	N HIGHLAND BLVD	0	0	35	32	Alligator	Mill & Overlay	\$16,071.09	25	140.0
414	N HIGHLAND BLVD	0	0	36	49	Depressions	Overlay	\$37,749.92	25	755.0
415	N HIGHLAND BLVD	0	0	36	49	Depressions	Overlay	\$12,730.67	62	102.7
416	N HIGHLAND BLVD	0	0	36	49	Depressions	Overlay	\$26,969.95	31	435.0
417	N HIGHLAND BLVD	11001	11249	33	61	Long/Trans	Chip Seal	\$3,370.52	25	813.5
418	N HIGHLAND BLVD	11001	11249	33	61	Long/Trans	Chip Seal	\$3,420.66	32	645.0
419	N HIGHLAND BLVD	11251	11439	34	68	Long/Trans	Chip Seal	\$6,195.29	24	1632.3
420	N HIGHLAND BLVD	11251	11439	35	32	Alligator	Mill & Overlay	\$55,427.94	32	377.2
421	N HIGHLAND BLVD	11441	11599	35	32	Alligator	Mill & Overlay	\$121,385.51	25	1057.4
422	N HIGHLAND BLVD	11441	11599	35	32	Alligator	Mill & Overlay	\$20,571.00	32	140.0
423	N HIGHLAND BLVD	11601	11799	36	49	Depressions	Overlay	\$37,749.92	25	755.0
424	N HIGHLAND BLVD	11601	11799	36	49	Depressions	Overlay	\$27,918.48	31	450.3
425	N HIGHLAND CIR	10805	10849	219	62	Block	Chip Seal	\$1,188.14	34	157.1
426	N HIGHLAND CIR	10851	10919	219	62	Block	Chip Seal	\$2,338.95	34	309.2
427	N HORIZON DR	11851	11899	105	80	Weathering	Slurry Seal	\$959.35	34	280.8
428	N HORIZON DR	11901	11949	105	80	Weathering	Slurry Seal	\$996.76	34	291.7
429	N THICA DR	11961	12089	107	50	Weathering	Overlay	\$125,543.11	34	920.2
430	N IVERSON LN	10401	10449	162	90	Patching	Slurry Seal	\$1,430.33	34	413.8
431	N IVERSON LN	10451	10549	162	90	Patching	Slurry Seal	\$2,180.63	34	630.8
432	N JANIE LN	10471	10549	212	70	Long/Trans	Chip Seal	\$4,470.84	34	340.7
433	N JANIE LN	10471	10549	213	90	Depressions	Do Nothing	\$0.00	34	189.9
434	N JANIE LN	10551	10569	213	90	Depressions	Do Nothing	\$0.00	34	161.9
435	N JANIE LN	10571	10599	214	90	Weathering	Slurry Seal	\$572.37	34	167.6
436	N JANIE LN	10571	10599	213	90	Depressions	Do Nothing	\$0.00	34	167.6
437	N JOSEPH LN	10725	10759	137	49	Depressions	Overlay	\$29,476.35	34	287.9
438	N JUPITER CIR	11821	11839	108	34	Depressions	Reconstruct	\$34,713.77	34	157.1
439	N JUPITER CIR	11841	11889	108	34	Depressions	Reconstruct	\$93,551.51	34	423.2
440	N KNIGHT AVE	10101	10499	210	100	None	Do Nothing	\$0.00	34	3654.3
441	N LARSEN AVE	10551	10619	155	48	Pothole	Overlay	\$33,457.62	34	345.4
442	N LARSEN AVE	10551	10619	154	80	Weathering	Slurry Seal	\$558.68	34	163.6
443	N LARSEN AVE	10621	10689	154	80	Weathering	Slurry Seal	\$1,231.20	34	360.6
444	N LIGHT HOUSE DR	12175	12229	102	86	Weathering	Slurry Seal	\$905.36	34	265.2
445	N LIGHT HOUSE DR	12331	12279	102	86	Weathering	Slurry Seal	\$1,176.43	34	344.6
446	N LIGHT HOUSE DR	12281	12329	102	86	Weathering	Slurry Seal	\$1,134.13	34	332.2
447	N LIGHT HOUSE DR	12331	12469	100	86	Weathering	Slurry Seal	\$1,828.48	34	536.3
448	N LIGHT HOUSE DR	12331	12469	102	86	Weathering	Slurry Seal	\$1,570.10	34	459.9
449	N LONE ROCK CIR	11551	11589	113	78	Weathering	Slurry Seal	\$990.67	34	282.2
450	N LONE ROCK CIR	11591	11599	113	78	Weathering	Slurry Seal	\$551.35	34	157.1

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
451	N MANOR CIR	11025	11059	128	55	Patching	Chip Seal	\$14,294.87	32	265.3
452	N MANOR CIR	11061	11079	128	55	Patching	Chip Seal	\$8,463.78	32	157.1
453	N MANOR DR	11001	11029	128	55	Patching	Chip Seal	\$12,856.16	32	238.6
454	N MANOR DR	11031	11069	128	55	Patching	Chip Seal	\$28,641.08	32	531.5
455	N MANOR DR	11071	11085	128	55	Patching	Chip Seal	\$8,463.84	32	157.1
456	N MAPLE HOLLOW CT	11431	11509	112	80	Weathering	Slurry Seal	\$1,796.36	34	520.6
457	N MAPLE HOLLOW CT	11511	11559	112	80	Weathering	Slurry Seal	\$1,226.19	34	355.3
458	N MAPLE HOLLOW CT	11561	11589	112	80	Weathering	Slurry Seal	\$542.06	34	157.1
459	N MEADOW DR	10691	10699	154	80	Weathering	Slurry Seal	\$611.46	34	179.1
460	N MERCER HOLLOW RD	11451	11499	114	58	Patching	Chip Seal	\$20,340.96	34	251.3
461	N MERCER HOLLOW RD	11501	11509	114	58	Patching	Chip Seal	\$13,129.14	34	162.2
462	N MERCER HOLLOW RD	11511	11549	114	58	Patching	Chip Seal	\$23,018.87	34	284.4
463	N MERCER HOLLOW RD	11551	11589	114	58	Patching	Chip Seal	\$25,346.22	34	313.2
464	N MERCER HOLLOW RD	11591	11599	114	58	Patching	Chip Seal	\$12,513.79	34	154.6
465	N MOUNTAIN SHADOWS LN	11001	11073	130	80	Long/Trans	Slurry Seal	\$2,167.78	34	585.5
466	N MOUNTAIN SHADOWS LN	11075	11089	130	80	Long/Trans	Slurry Seal	\$581.58	34	157.1
467	N MOUNTAIN VIEW DR	9861	9889	186	78	Long/Trans	Slurry Seal	\$861.33	34	246.7
468	N MOUNTAIN VIEW DR	9891	9959	186	78	Long/Trans	Slurry Seal	\$1,251.64	30	406.3
469	N MOUNTAIN VIEW DR	9891	9959	186	78	Long/Trans	Slurry Seal	\$377.05	34	108.0
470	N MOUNTAIN VIEW DR	9961	10049	174	58	Long/Trans	Slurry Seal	\$37,368.84	34	355.5
471	N MOUNTAIN VIEW DR	9961	10049	186	78	Long/Trans	Slurry Seal	\$743.04	30	241.2
472	N MOUNTAIN VIEW DR	10051	10149	174	58	Long/Trans	Overlay	\$39,845.00	34	375.4
473	N MOUNTAIN VIEW DR	10051	10149	173	30	Depressions	Reconstruct	\$70,025.18	34	316.9
474	N MOUNTAIN VIEW DR	10151	10219	173	30	Depressions	Reconstruct	\$74,160.93	34	335.6
475	N MOUNTAIN VIEW DR	10151	10219	172	60	Aligator	Chip Seal	\$6,447.51	34	219.5
476	N MOUNTAIN VIEW DR	10231	10239	172	60	Aligator	Chip Seal	\$6,153.51	34	209.5
477	N MOUNTAIN VIEW DR	10241	10273	172	60	Aligator	Chip Seal	\$4,613.51	34	157.1
478	N MOUNTAIN VIEW DR	10015	10039	208	78	Block	Slurry Seal	\$665.43	34	157.1
479	N MYSTIC CIR	10041	10129	208	78	Block	Slurry Seal	\$2,432.67	34	574.2
480	N MYSTIC CIR	10131	10159	208	78	Block	Slurry Seal	\$1,554.44	34	366.9
481	N MYSTIC DR	10161	10219	208	78	Block	Slurry Seal	\$1,494.42	34	352.8
482	N MYSTIC DR	10221	10279	209	80	Pothole	Do Nothing	\$0.00	34	335.9
483	N MYSTIC DR	10281	10319	209	80	Pothole	Do Nothing	\$0.00	34	330.6
484	N MYSTIC DR	10321	10399	209	80	Pothole	Do Nothing	\$0.00	34	530.6
485	N MYSTIC HOLW	10151	10179	208	78	Block	Slurry Seal	\$665.44	34	157.1
486	N MYSTIC HOLW	10181	10229	208	78	Block	Slurry Seal	\$1,432.54	34	338.2
487	N MYSTIC HOLW	10231	10259	209	80	Pothole	Do Nothing	\$0.00	34	409.3
488	N MYSTIC HOLW	10261	10279	209	80	Pothole	Do Nothing	\$0.00	34	157.1
489	N NATALIE CT	10821	10849	137	49	Depressions	Overlay	\$16,082.41	34	441.2
490	N NATALIE CT	10851	10899	137	49	Depressions	Overlay	\$45,172.54	34	157.1
491	N NORMANDY WAY	11241	11299	118	90	Weathering	Slurry Seal	\$2,976.80	34	867.6
492	N NORMANDY WAY	11301	11349	118	90	Weathering	Slurry Seal	\$1,188.12	34	346.3
493	N OWL CIR	10475	10499	162	90	Patching	Slurry Seal	\$543.00	34	157.1
494	N OWL CIR	10501	10529	162	90	Patching	Slurry Seal	\$1,013.63	34	293.2
495	N OXFORD CT	9831	9849	201	90	Patching	Slurry Seal	\$486.62	30	157.1

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
496	N OXFORD CT	9851	9915	201	90	Patching	Slurry Seal	\$1,861.48	30	600.9
497	N PARK CIR	11115	11173	221	86	Weathering	Slurry Seal	\$1,267.45	34	365.4
498	N PARK DR	10985	11149	221	86	Weathering	Slurry Seal	\$5,133.16	30	1677.1
499	N PARK DR	11151	11189	221	86	Weathering	Slurry Seal	\$954.40	34	275.1
500	N PARK DR	11191	11223	221	86	Weathering	Slurry Seal	\$1,003.12	34	289.2
501	N PARK DR	11225	11279	221	86	Weathering	Slurry Seal	\$1,030.11	34	297.0
502	N PARK DR	11281	11299	221	86	Weathering	Slurry Seal	\$515.95	34	148.7
503	N PENTON AVE	10501	10523	148	90	Weathering	Slurry Seal	\$944.49	34	277.8
504	N PONCE DE LEON DR	12601	12699	100	86	Weathering	Slurry Seal	\$2,496.55	34	732.2
505	N PROVENCE CIR	11231	11249	118	90	Weathering	Slurry Seal	\$532.89	34	155.3
506	N PROVENCE CIR	11251	11253	118	90	Weathering	Slurry Seal	\$538.95	34	157.1
507	N QUAIL CT	10435	10449	162	90	Patching	Slurry Seal	\$543.00	34	157.1
508	N QUAIL CT	10451	10499	162	90	Patching	Slurry Seal	\$774.18	34	224.0
509	N RIVER BEND RD	11361	11399	116	58	Pothole	Mill & Overlay	\$37,793.42	34	310.2
510	N RIVER BEND RD	11401	11459	116	58	Patching	Mill & Overlay	\$56,273.12	34	461.9
511	N RIVERSIDE LN	10001	10009	203	99	Patching	Do Nothing	\$0.00	30	157.1
512	N RIVERSIDE LN	10011	10029	203	99	Patching	Do Nothing	\$0.00	30	124.4
513	N RIVERSIDE LN	10031	10149	203	99	Patching	Do Nothing	\$0.00	30	769.2
514	N RIVERSIDE LN	10151	10189	203	99	Patching	Do Nothing	\$0.00	30	197.4
515	N RIVERSIDE LN	10191	10199	203	99	Weathering	Do Nothing	\$0.00	30	138.4
516	N SAMPSON DR	11141	11199	127	90	Weathering	Slurry Seal	\$830.09	34	244.1
517	N SAMPSON DR	11201	11239	126	80	Long/Trans	Slurry Seal	\$975.72	34	259.3
518	N SAMPSON DR	11241	11299	126	80	Long/Trans	Slurry Seal	\$1,827.07	34	485.6
519	N SAMPSON DR	11301	11389	126	80	Long/Trans	Slurry Seal	\$1,654.24	34	439.6
520	N SHORELINE DR	11151	11279	221	86	Weathering	Slurry Seal	\$2,885.80	34	831.9
521	N SKY LINE DR W	11511	11549	114	58	Patching	Chip Seal	\$22,903.32	34	283.0
522	N SKY LINE DR W	11551	11589	114	58	Patching	Chip Seal	\$21,977.38	34	271.5
523	N SPRUCE DR	11001	11049	129	90	Pothole	Do Nothing	\$0.00	34	334.6
524	N SPRUCE DR	11051	11099	129	90	Pothole	Do Nothing	\$0.00	34	659.9
525	N SPRUCE DR	11101	11149	129	90	Pothole	Do Nothing	\$0.00	34	157.0
526	N STONE CREEK DR	11175	11289	124	70	Weathering	Chip Seal	\$4,728.38	34	248.6
527	N STONE CREEK HOLW	11245	11249	124	70	Weathering	Chip Seal	\$2,988.18	34	157.1
528	N STONE CREEK HOLW	11251	11279	124	70	Weathering	Chip Seal	\$1,918.37	34	100.8
529	N STONESHIRE	10641	10689	152	90	Pothole	Do Nothing	\$0.00	34	299.2
530	N STONESHIRE	10691	10799	151	66	Long/Trans	Chip Seal	\$16,766.89	34	274.2
531	N STONESHIRE	10691	10799	152	90	Pothole	Do Nothing	\$0.00	34	172.8
532	N SUMMERFIELD CT	11531	11579	117	80	Weathering	Slurry Seal	\$391.61	34	114.6
533	N SUMMERFIELD CT	11581	11599	117	80	Weathering	Slurry Seal	\$536.70	34	157.1
534	N SUNRISE CIR	11631	11689	110	54	Patching	Mill & Overlay	\$60,629.72	34	385.3
535	N SUNRISE CIR	11691	11719	110	54	Patching	Mill & Overlay	\$24,717.51	34	157.1
536	N SUNSET HILLS DR	11441	11599	113	78	Weathering	Slurry Seal	\$3,962.15	34	1128.8
537	N SUNSET HILLS DR	11601	11683	111	75	Patching	Chip Seal	\$28,768.51	34	657.0
538	N SUNSET HILLS DR	11685	11739	111	75	Patching	Chip Seal	\$18,967.64	34	433.2
539	N SUNSET HILLS DR	11741	11753	111	75	Patching	Chip Seal	\$6,023.00	34	137.6
540	N SUNSET HILLS DR	11755	11769	111	75	Patching	Chip Seal	\$6,878.00	34	157.1

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
541	N TIMBER RIDGE LN	12555	12599	101	70	Long/Trans	Chip Seal	\$6,921.41	34	253.0
542	N TIMBERLINE DR	12221	12339	44	40	Patching	Mill & Overlay	\$105,977.36	34	721.1
543	N TIMBERLINE DR	12341	12553	101	70	Long/Trans	Chip Seal	\$38,846.26	34	1419.8
544	N TOWN CENTER BLVD	0	0	144	60	Pothole	Mill & Overlay	\$47,521.81	17	851.3
545	N TOWN CENTER BLVD	10851	10999	144	60	Pothole	Mill & Overlay	\$47,457.54	17	850.1
546	N TOWN CENTER EAST	10601	10609	146	68	Long/Trans	Chip Seal	\$2,349.24	34	354.3
547	N TOWN CENTER EAST	10611	10699	146	68	Long/Trans	Chip Seal	\$2,453.38	34	370.0
548	N TOWN CENTER EAST	10701	10699	227	78	Long/Trans	Slurry Seal	\$1,442.69	34	250.1
550	N TOWN CENTER EAST	10701	10819	144	60	Pothole	Mill & Overlay	\$67,174.32	32	639.3
551	N TOWN CENTER EAST	10821	10849	144	60	Pothole	Mill & Overlay	\$21,481.56	34	192.4
552	N TOWN CENTER WEST	10851	10899	144	60	Pothole	Mill & Overlay	\$41,580.54	34	372.4
553	N TOWN CENTER WEST	10851	10899	144	60	Pothole	Mill & Overlay	\$39,838.90	34	356.8
554	N TOWN CENTER WEST	10701	10809	144	60	Pothole	Mill & Overlay	\$64,133.50	34	574.4
555	N TOWN CENTER WEST	10811	10819	144	60	Pothole	Mill & Overlay	\$8,848.25	34	79.3
556	N TOWN CENTER WEST	10821	10849	144	60	Pothole	Mill & Overlay	\$19,753.49	34	176.9
557	N VILLAGE DR	10751	10799	152	90	Pothole	Do Nothing	\$0.00	34	311.2
558	N WALKER LN	10681	10799	145	86	Weathering	Slurry Seal	\$2,256.76	34	648.1
559	N WASATCH DR	10401	10499	148	90	Weathering	Slurry Seal	\$1,375.83	34	404.7
560	N WELLINGTON CT	10951	10999	220	58	Block	Overlay	\$19,635.64	34	288.8
561	N WELLINGTON CT	9961	9989	201	90	Patching	Slurry Seal	\$713.00	30	230.1
562	N WEST CRIMSON CT	9871	9873	194	90	Weathering	Slurry Seal	\$486.63	30	157.1
563	N WEST CRIMSON CT	9875	9903	194	90	Weathering	Slurry Seal	\$729.39	34	214.5
564	N WEST JERLING DR	10621	10699	215	73	Block	Chip Seal	\$534.06	34	157.1
565	N WEST PANORAMA DR	10801	10873	219	62	Block	Chip Seal	\$21,152.20	34	851.0
566	N WEST PANORAMA DR	10875	10909	219	62	Block	Chip Seal	\$2,357.99	34	311.7
567	N WESTFIELD COVE DR	11835	11839	104	86	Weathering	Slurry Seal	\$1,659.71	34	219.4
568	N WESTFIELD COVE DR	11841	11869	104	86	Weathering	Slurry Seal	\$535.59	34	157.1
569	N WESTFIELD COVE DR	11871	11989	104	86	Weathering	Slurry Seal	\$598.78	34	175.6
570	N WESTFIELD COVE DR	11871	11989	103	72	Long/Trans	Slurry Seal	\$2,051.73	34	601.7
571	N WESTWOOD LN	10135	10199	168	54	Alligator	Chip Seal	\$16,793.47	34	185.5
572	N WESTWOOD LN	10201	10249	168	54	Alligator	Chip Seal	\$3,563.26	34	157.1
573	N WILDELOWER LN	12341	12469	101	70	Long/Trans	Chip Seal	\$12,973.49	34	571.9
574	N WILDELOWER LN	12471	12529	101	70	Long/Trans	Chip Seal	\$22,275.61	34	184.1
575	N WILDELOWER LN	12531	12599	101	70	Long/Trans	Chip Seal	\$11,594.98	34	423.8
576	N WINDSOR LN	10511	10539	217	40	Pothole	Chip Seal	\$10,265.83	34	375.2
577	N WOODLAND DR	11301	11309	125	50	Depressions	Reconstruct	\$44,901.02	25	276.3
578	N WOODLAND DR	11311	11359	125	50	Depressions	Overlay	\$22,706.06	34	240.7
579	N WOODLAND DR	11361	11389	125	50	Depressions	Overlay	\$26,322.64	34	279.0
580	N WOODLAND DR	11391	11429	125	50	Depressions	Overlay	\$17,560.48	34	186.2
581	N YORKSHIRE CT	9891	9909	201	90	Patching	Slurry Seal	\$24,274.40	34	257.3
582	N YORKSHIRE CT	9911	9969	201	90	Patching	Slurry Seal	\$486.63	30	157.1
583	N YORKSHIRE CT	10191	10209	203	99	Patching	Slurry Seal	\$1,049.41	30	338.7
584	P1			235	78	Block	Do Nothing	\$0.00	30	108.6
585	P2			224	53	Block	Slurry Seal	\$1,909.05	32	479.7
							Overlay	\$18,969.98	39	243.2

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
586	P3			226	100	None	Do Nothing	\$0.00	39	424.7
587	W 10030 NORTH ST	5421	5479	226	100	None	Do Nothing	\$0.00	39	433.5
588	W 10030 NORTH ST	5481	5599	207	78	Pothole	Do Nothing	\$0.00	34	415.0
590	W 10030 NORTH ST	6581	6609	170	74	Alligator	Chip Seal	\$4,980.94	34	759.8
591	W 10030 NORTH ST	6611	6689	170	74	Alligator	Chip Seal	\$11,588.86	34	210.9
592	W 10040 NORTH ST	5733	5749	202	80	Long/Trans	Slurry Seal	\$562.32	34	490.7
593	W 10040 NORTH ST	5751	5759	202	80	Long/Trans	Slurry Seal	\$1,281.00	34	157.1
594	W 10040 NORTH ST	5801	5841	202	80	Long/Trans	Slurry Seal	\$1,180.10	34	329.6
595	W 10050 NORTH ST	6001	6149	174	58	Long/Trans	Overlay	\$118,647.81	34	1117.8
596	W 10050 NORTH ST	6151	6299	174	58	Long/Trans	Overlay	\$113,685.97	34	1071.0
597	W 10050 NORTH ST	6691	6799	167	75	Alligator	Chip Seal	\$6,653.35	34	705.3
598	W 10080 NORTH ST	5425	5439	207	78	Pothole	Do Nothing	\$0.00	34	157.1
599	W 10080 NORTH ST	5441	5479	207	78	Pothole	Do Nothing	\$0.00	34	252.5
600	W 10080 NORTH ST	5481	5599	207	78	Pothole	Do Nothing	\$0.00	34	751.3
601	W 10100 NORTH ST	4801	4999	210	100	None	Do Nothing	\$0.00	34	1929.9
602	W 10100 NORTH ST	5681	5749	203	99	Patching	Do Nothing	\$0.00	30	401.0
603	W 10100 NORTH ST	5751	5799	204	78	Patching	Slurry Seal	\$1,712.56	34	461.2
604	W 10100 NORTH ST	5801	5889	204	78	Patching	Slurry Seal	\$1,277.41	34	344.0
605	W 10100 NORTH ST	5801	5891	204	78	Patching	Slurry Seal	\$768.87	30	234.7
606	W 10100 NORTH ST	5951	5949	205	50	Weathering	Mill & Overlay	\$32,783.80	29	376.8
607	W 10100 NORTH ST	6581	6689	170	74	Alligator	Chip Seal	\$16,723.71	29	401.8
608	W 10120 NORTH ST	6741	6759	167	75	Alligator	Chip Seal	\$15,749.11	34	666.9
609	W 10125 NORTH ST	5441	5479	167	75	Alligator	Chip Seal	\$1,481.69	34	157.1
610	W 10125 NORTH ST	5481	5599	207	78	Pothole	Do Nothing	\$3,100.99	34	328.7
611	W 10130 NORTH ST	5481	5599	207	78	Pothole	Do Nothing	\$0.00	34	295.3
612	W 10130 NORTH ST	6001	6299	173	30	Depressions	Do Nothing	\$0.00	34	755.4
613	W 10150 NORTH ST	6801	6889	166	68	Patching	Chip Seal	\$453,389.14	34	2051.5
614	W 10150 NORTH ST	6891	6959	166	68	Patching	Chip Seal	\$6,901.98	34	615.9
615	W 10180 NORTH ST	5401	5479	207	78	Pothole	Do Nothing	\$4,996.08	34	445.8
616	W 10180 NORTH ST	5481	5599	207	78	Pothole	Do Nothing	\$0.00	34	593.9
617	W 10200 NORTH ST	6571	6579	170	74	Alligator	Do Nothing	\$0.00	34	748.3
618	W 10200 NORTH ST	6591	6609	170	74	Alligator	Chip Seal	\$4,441.56	34	188.1
619	W 10200 NORTH ST	6611	6629	170	74	Alligator	Chip Seal	\$4,710.91	34	199.5
620	W 10205 NORTH ST	6741	6759	167	75	Alligator	Chip Seal	\$3,709.58	34	157.1
621	W 10205 NORTH ST	6761	6799	167	75	Alligator	Chip Seal	\$1,481.68	34	157.1
622	W 10205 NORTH ST	6801	6889	166	68	Patching	Chip Seal	\$3,142.68	34	333.2
623	W 10220 NORTH ST	6239	6239	172	60	Alligator	Chip Seal	\$5,825.99	34	519.9
624	W 10220 NORTH ST	6241	6299	172	60	Alligator	Chip Seal	\$4,613.51	34	157.1
625	W 10220 NORTH ST	6301	6359	172	60	Alligator	Chip Seal	\$11,028.02	34	157.1
626	W 10220 NORTH ST	6361	6369	172	60	Alligator	Chip Seal	\$16,032.36	34	375.5
627	W 10250 NORTH ST	6401	6449	171	32	Weathering	Chip Seal	\$4,613.52	34	545.9
628	W 10250 NORTH ST	6451	6579	170	74	Alligator	Reconstruct	\$52,977.81	34	157.1
629	W 10250 NORTH ST	6581	6629	169	49	Alligator	Chip Seal	\$23,777.73	34	239.7
630	W 10250 NORTH ST	6581	6629	169	49	Alligator	Overlay	\$44,767.07	34	1006.9

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
631	W 10250 NORTH ST	6631	6649	169	49	Alligator	Overlay	\$15,744.20	34	156.3
632	W 10250 NORTH ST	6651	6679	168	54	Alligator	Chip Seal	\$2,343.17	34	103.3
633	W 10250 NORTH ST	6681	6699	168	54	Alligator	Chip Seal	\$4,508.95	34	198.8
634	W 10250 NORTH ST	6701	6799	168	54	Alligator	Chip Seal	\$12,847.85	34	566.4
635	W 10300 NORTH ST	4681	4699	211	70	Long/Trans	Chip Seal	\$2,061.49	34	157.1
636	W 10300 NORTH ST	4701	4729	211	70	Long/Trans	Chip Seal	\$2,507.08	34	191.0
637	W 10300 NORTH ST	6531	6579	169	49	Alligator	Overlay	\$42,477.62	34	421.8
638	W 10300 NORTH ST	6801	6899	164	80	Long/Trans	Slurry Seal	\$1,362.63	34	381.0
639	W 10300 NORTH ST	6801	6899	164	80	Long/Trans	Slurry Seal	\$795.35	34	222.4
640	W 10300 NORTH ST	6901	6959	164	80	Long/Trans	Slurry Seal	\$1,588.04	34	444.0
641	W 10370 NORTH ST	4731	4799	211	70	Long/Trans	Chip Seal	\$5,686.08	34	433.3
642	W 10380 NORTH ST	6531	6579	169	49	Alligator	Overlay	\$35,149.48	34	349.0
643	W 10380 NORTH ST	6581	6679	169	49	Alligator	Overlay	\$54,030.53	34	536.5
644	W 10400 NORTH ST	5301	5599	3	48	Alligator	Overlay	\$180,956.32	44	1605.6
645	W 10400 NORTH ST	5601	5729	3	48	Alligator	Overlay	\$116,928.25	34	1342.6
646	W 10400 NORTH ST	5731	5999	3	48	Alligator	Overlay	\$96,630.89	29	1300.8
647	W 10400 NORTH ST	6001	6299	2	27	Pothole	Reconstruct	\$430,350.77	34	1947.3
648	W 10400 NORTH ST	6301	6399	2	27	Pothole	Reconstruct	\$141,528.20	30	725.8
649	W 10400 NORTH ST	6401	6569	1	29	Alligator	Mill & Overlay	\$124,430.91	37	953.0
650	W 10400 NORTH ST	6571	6579	1	29	Alligator	Mill & Overlay	\$69,157.75	44	445.4
651	W 10400 NORTH ST	6581	6749	1	29	Alligator	Mill & Overlay	\$107,166.07	44	690.2
652	W 10400 NORTH ST	6581	6749	1	29	Alligator	Chip Seal	\$9,698.46	44	264.8
653	W 10400 NORTH ST	6751	6799	223	48	Alligator	Chip Seal	\$11,465.23	44	313.1
654	W 10400 NORTH ST	6829	6829	0	52	Rutting	Mill & Overlay	\$47,855.79	44	205.5
655	W 10400 NORTH ST	6831	6899	0	52	Rutting	Mill & Overlay	\$94,956.08	44	407.8
656	W 10400 NORTH ST	6901	6959	0	52	Rutting	Mill & Overlay	\$121,984.21	44	523.9
657	W 10400 NORTH ST	6961	6999	0	52	Rutting	Mill & Overlay	\$34,949.57	44	150.1
658	W 10400 NORTH ST	7001	7049	0	52	Rutting	Mill & Overlay	\$35,822.83	44	153.9
659	W 10430 NORTH ST	7051	7069	0	52	Rutting	Mill & Overlay	\$85,888.28	44	368.9
660	W 10430 NORTH ST	6751	6789	161	46	Alligator	Chip Seal	\$13,340.48	34	281.5
661	W 10430 NORTH ST	6791	6859	161	46	Alligator	Chip Seal	\$19,805.34	34	418.0
662	W 10480 NORTH ST	5281	5469	147	80	Long/Trans	Slurry Seal	\$3,117.93	34	830.8
663	W 10480 NORTH ST	5471	5599	147	80	Long/Trans	Slurry Seal	\$8,238.03	34	862.8
664	W 10480 NORTH ST	6221	6249	158	42	Patching	Mill & Overlay	\$28,315.60	34	157.1
665	W 10480 NORTH ST	6251	6273	158	42	Patching	Mill & Overlay	\$41,327.14	34	229.3
666	W 10500 NORTH ST	6275	6399	158	42	Patching	Mill & Overlay	\$161,271.61	34	894.7
667	W 10550 NORTH ST	5901	5999	153	78	Long/Trans	Slurry Seal	\$2,361.97	34	638.2
668	W 10550 NORTH ST	6001	6149	155	48	Pothole	Overlay	\$99,115.86	34	1023.2
669	W 10550 NORTH ST	6151	6193	155	48	Pothole	Overlay	\$29,744.29	34	307.1
670	W 10570 NORTH ST	5875	5899	153	78	Long/Trans	Slurry Seal	\$1,038.35	34	280.6
671	W 10570 NORTH ST	6251	6399	157	70	Long/Trans	Chip Seal	\$40,431.04	34	976.0
672	W 10600 NORTH ST	5401	5469	146	68	Long/Trans	Chip Seal	\$2,020.54	34	304.7
673	W 10600 NORTH ST	5471	5549	146	68	Long/Trans	Chip Seal	\$4,272.58	34	644.4
674	W 10600 NORTH ST	5551	5599	146	68	Long/Trans	Chip Seal	\$1,553.70	34	234.3
675	W 10610 NORTH ST	5371	5399	146	68	Long/Trans	Chip Seal	\$2,395.26	34	361.2

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
676	W 10620 NORTH ST	0	0	149	90	Weathering	Slurry Seal	\$350.55	34	102.5
677	W 10620 NORTH ST	0	0	149	90	Weathering	Slurry Seal	\$193.24	34	56.5
678	W 10620 NORTH ST	0	0	149	90	Weathering	Slurry Seal	\$208.99	34	61.1
679	W 10620 NORTH ST	5601	5659	149	90	Weathering	Slurry Seal	\$1,367.83	34	399.8
680	W 10620 NORTH ST	5661	5719	149	90	Weathering	Slurry Seal	\$1,069.58	34	312.6
681	W 10620 NORTH ST	5721	5799	149	90	Weathering	Slurry Seal	\$1,877.00	34	548.6
682	W 10620 NORTH ST	5901	5999	153	78	Long/Trans	Slurry Seal	\$2,366.48	34	639.5
683	W 10630 NORTH ST	6325	6349	156	86	Weathering	Slurry Seal	\$541.48	34	157.1
684	W 10630 NORTH ST	6351	6399	156	86	Weathering	Slurry Seal	\$1,540.63	34	446.9
685	W 10670 NORTH ST	6341	6399	156	86	Weathering	Slurry Seal	\$1,575.48	34	457.0
686	W 10680 NORTH ST	5491	5529	227	78	Long/Trans	Slurry Seal	\$1,868.57	52	211.8
687	W 10680 NORTH ST	5601	5719	225	60	Bumps	Overlay	\$53,756.88	34	790.5
688	W 10680 NORTH ST	5721	5739	225	60	Bumps	Overlay	\$17,743.85	34	260.9
689	W 10680 NORTH ST	5741	5765	225	60	Bumps	Overlay	\$10,681.57	34	157.1
690	W 10700 NORTH ST	5225	5299	218	80	Depressions	Do Nothing	\$0.00	34	446.7
691	W 10740 NORTH ST	5261	5269	218	80	Depressions	Do Nothing	\$0.00	34	145.3
692	W 10740 NORTH ST	5271	5289	218	80	Depressions	Do Nothing	\$0.00	34	157.1
693	W 10760 NORTH ST	6091	6099	139	42	Alligator	Mill & Overlay	\$18,903.63	34	157.1
694	W 10760 NORTH ST	6101	6119	139	42	Alligator	Mill & Overlay	\$12,795.90	34	106.3
695	W 10760 NORTH ST	6121	6199	139	42	Alligator	Mill & Overlay	\$62,839.04	34	222.2
696	W 10760 NORTH ST	6401	6509	137	49	Depressions	Overlay	\$79,797.76	34	779.4
697	W 10770 NORTH ST	6511	6599	137	49	Depressions	Overlay	\$79,643.29	34	777.9
698	W 10770 NORTH ST	5601	5719	150	21	Alligator	Reconstruct	\$167,535.58	34	758.1
699	W 10770 NORTH ST	5721	5749	150	21	Alligator	Reconstruct	\$51,615.96	34	233.6
700	W 10770 NORTH ST	5751	5759	150	21	Alligator	Reconstruct	\$23,096.25	34	104.5
701	W 10770 NORTH ST	5761	5779	150	21	Alligator	Reconstruct	\$34,714.81	34	157.1
702	W 10800 NORTH ST	5261	5269	218	80	Depressions	Do Nothing	\$0.00	34	136.6
703	W 10800 NORTH ST	5271	5289	218	80	Depressions	Do Nothing	\$0.00	34	157.1
704	W 10800 NORTH ST	5531	5559	145	86	Weathering	Slurry Seal	\$807.89	34	232.0
705	W 10800 NORTH ST	5751	5799	150	21	Alligator	Reconstruct	\$74,551.56	34	337.3
706	W 10800 NORTH ST	5751	5799	151	66	Long/Trans	Chip Seal	\$10,847.58	34	177.4
707	W 10800 NORTH ST	5801	5869	151	66	Long/Trans	Chip Seal	\$19,788.59	34	323.6
708	W 10800 NORTH ST	5871	5919	151	66	Long/Trans	Chip Seal	\$20,176.82	34	329.9
709	W 10800 NORTH ST	5921	5999	151	66	Long/Trans	Chip Seal	\$31,646.12	34	517.5
710	W 10830 NORTH ST	6151	6199	139	42	Alligator	Mill & Overlay	\$40,285.04	34	334.8
711	W 10830 NORTH ST	6201	6399	139	42	Alligator	Mill & Overlay	\$165,262.67	34	1373.3
712	W 10850 NORTH ST	5261	5269	218	80	Depressions	Do Nothing	\$0.00	34	129.0
713	W 10850 NORTH ST	5271	5279	218	80	Depressions	Do Nothing	\$0.00	34	157.1
714	W 10880 NORTH ST	5871	5929	140	34	Alligator	Mill & Overlay	\$40,101.67	34	327.9
715	W 10890 NORTH ST	6265	6289	138	86	Patching	Slurry Seal	\$540.42	34	157.1
716	W 10890 NORTH ST	6291	6329	138	86	Patching	Slurry Seal	\$1,340.23	34	389.6
717	W 10890 NORTH ST	6331	6399	138	86	Patching	Slurry Seal	\$1,664.88	34	483.9
718	W 10900 NORTH ST	5251	5279	218	80	Depressions	Do Nothing	\$0.00	34	342.6
719	W 10900 NORTH ST	5751	5799	142	80	Long/Trans	Slurry Seal	\$1,144.24	32	338.1
720	W 10900 NORTH ST	5751	5799	141	86	Long/Trans	Slurry Seal	\$554.23	32	164.5

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
721	W 10900 NORTH ST	5801	5869	141	86	Long/Trans	Slurry Seal	\$624.04	34	174.4
722	W 10900 NORTH ST	5801	5869	140	34	Alligator	Mill & Overlay	\$20,496.51	34	167.6
723	W 10925 NORTH ST	5871	5929	140	34	Alligator	Mill & Overlay	\$39,926.12	34	326.4
724	W 10930 NORTH ST	5601	5679	143	78	Long/Trans	Slurry Seal	\$1,827.61	34	520.1
725	W 10930 NORTH ST	5681	5699	143	78	Long/Trans	Slurry Seal	\$552.00	34	157.1
726	W 10940 NORTH ST	6271	6329	138	86	Patching	Slurry Seal	\$1,198.93	34	348.5
727	W 11030 NORTH ST	5601	5649	134	78	Long/Trans	Slurry Seal	\$1,074.47	34	290.8
728	W 11060 NORTH ST	5455	5499	133	78	Block	Slurry Seal	\$1,573.95	34	393.6
729	W 11100 NORTH ST	5101	5269	131	75	Long/Trans	Slurry Seal	\$55,333.08	34	1224.6
730	W 11130 NORTH ST	4875	4899	127	90	Weathering	Slurry Seal	\$534.06	34	157.1
731	W 11130 NORTH ST	5275	5299	132	50	Alligator	Overlay	\$20,348.79	25	177.2
732	W 11140 NORTH ST	5861	5999	119	70	Long/Trans	Chip Seal	\$43,086.17	32	708.7
733	W 11140 NORTH ST	5861	5999	119	70	Long/Trans	Chip Seal	\$6,041.49	30	106.0
734	W 11140 NORTH ST	5861	5999	119	70	Long/Trans	Chip Seal	\$6,383.46	42	80.0
735	W 11200 NORTH ST	4547	4799	6	49	Bumps	Overlay	\$37,739.74	22	857.7
736	W 11200 NORTH ST	4547	4799	6	49	Bumps	Overlay	\$36,167.93	22	822.0
737	W 11200 NORTH ST	4801	4879	7	75	Long/Trans	Slurry Seal	\$15,816.03	42	513.2
738	W 11200 NORTH ST	4881	5099	7	75	Long/Trans	Slurry Seal	\$31,404.60	34	1258.7
739	W 11200 NORTH ST	4881	5099	7	75	Long/Trans	Slurry Seal	\$6,688.20	42	217.0
740	W 11200 NORTH ST	5101	5273	7	75	Long/Trans	Slurry Seal	\$14,877.91	31	654.0
741	W 11200 NORTH ST	5101	5273	7	75	Long/Trans	Slurry Seal	\$15,344.54	41	510.0
742	W 11200 NORTH ST	5275	5299	8	66	Depressions	Slurry Seal	\$7,978.11	32	177.9
743	W 11200 NORTH ST	5301	5499	8	66	Depressions	Slurry Seal	\$29,246.22	32	652.0
744	W 11200 NORTH ST	5301	5499	8	66	Depressions	Slurry Seal	\$39,927.60	44	647.4
745	W 11200 NORTH ST	5501	5549	8	66	Depressions	Slurry Seal	\$20,361.03	44	330.1
746	W 11200 NORTH ST	5551	5599	8	66	Depressions	Slurry Seal	\$21,135.83	44	342.7
747	W 11200 NORTH ST	5601	5649	8	66	Depressions	Slurry Seal	\$15,031.32	34	315.4
748	W 11200 NORTH ST	5651	5653	122	48	Alligator	Overlay	\$7,062.47	34	52.0
749	W 11200 NORTH ST	5655	5665	122	48	Alligator	Overlay	\$21,350.22	34	157.1
750	W 11250 NORTH ST	5831	5999	228	75	Edge Crack	Chip Seal	\$2,267.44	22	645.4
751	W 11250 NORTH ST	5831	5999	9	42	Block	Mill & Overlay	\$98,344.72	34	515.0
752	W 11270 NORTH ST	5621	5623	122	48	Alligator	Overlay	\$27,590.20	34	203.0
753	W 11270 NORTH ST	5625	5649	122	48	Alligator	Overlay	\$21,350.37	34	157.1
754	W 11350 NORTH ST	5501	5599	123	70	Long/Trans	Chip Seal	\$46,022.10	34	620.8
755	W 11350 NORTH ST	5601	5649	122	48	Alligator	Overlay	\$41,181.38	34	303.0
756	W 11350 NORTH ST	5651	5709	122	48	Alligator	Overlay	\$63,226.45	34	465.2
757	W 11350 NORTH ST	5711	5829	122	48	Alligator	Overlay	\$76,769.65	34	564.8
758	W 11350 NORTH ST	5711	5829	120	48	Block	Overlay	\$27,770.22	34	263.1
759	W 11350 NORTH ST	5831	5859	121	86	Weathering	Slurry Seal	\$784.61	34	230.8
760	W 11350 NORTH ST	5861	5879	121	86	Weathering	Slurry Seal	\$534.07	34	157.1
761	W 11580 NORTH ST	6001	6039	117	80	Patching	Chip Seal	\$6,788.46	52	292.4
762	W 11800 NORTH ST	6101	6149	4	75	Patching	Chip Seal	\$16,165.72	52	696.3
763	W 11800 NORTH ST	6151	6299	4	75	Patching	Chip Seal	\$11,818.01	40	661.7
764	W 11800 NORTH ST	6151	6299	4	75	Patching	Chip Seal	\$8,126.01	52	350.0
765	W 11800 NORTH ST	6151	6299	4	75	Patching	Chip Seal			

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
766	W 11800 NORTH ST	6301	6399	5	42	Alligator	Mill & Overlay	\$145,956.43	52	667.7
767	W 11800 NORTH ST	6401	6599	5	42	Alligator	Mill & Overlay	\$200,582.09	46	1037.3
768	W 11800 NORTH ST	6401	6599	5	42	Alligator	Mill & Overlay	\$49,180.85	52	225.0
769	W 11830 NORTH ST	6021	6033	106	70	Long/Trans	Chip Seal	\$10,146.27	34	157.1
770	W 11830 NORTH ST	6035	6039	106	70	Long/Trans	Chip Seal	\$3,964.53	34	61.4
771	W 11860 NORTH ST	6021	6039	106	70	Long/Trans	Chip Seal	\$10,146.28	34	157.1
772	W 11860 NORTH ST	6041	6043	106	70	Long/Trans	Chip Seal	\$10,710.61	34	165.8
773	W 1500 NORTH ST	1	19	12	38	Alligator	Mill & Overlay	\$3,108.06	36	27.4
774	W 9500 NORTH ST	6501	6559	182	50	Weathering	Overlay	\$32,389.98	34	211.2
775	W 9500 NORTH ST	6561	6619	182	50	Weathering	Overlay	\$35,664.18	34	232.6
776	W 9500 NORTH ST	6561	6619	180	68	Weathering	Chip Seal	\$2,277.54	34	147.7
777	W 9500 NORTH ST	6621	6799	180	68	Weathering	Chip Seal	\$19,524.06	34	1266.1
778	W 9600 NORTH ST	5601	5649	12	38	Alligator	Mill & Overlay	\$9,106.97	25	115.8
779	W 9600 NORTH ST	5601	5649	229	22	Patching	Reconstruct	\$31,937.28	25	196.5
780	W 9600 NORTH ST	5651	5699	12	38	Alligator	Mill & Overlay	\$30,537.51	36	269.6
781	W 9600 NORTH ST	5701	5739	12	38	Alligator	Mill & Overlay	\$33,310.55	36	294.1
782	W 9600 NORTH ST	5741	5759	12	38	Alligator	Mill & Overlay	\$18,202.19	36	160.7
783	W 9600 NORTH ST	5855	5859	12	38	Alligator	Mill & Overlay	\$12,118.37	36	107.0
784	W 9600 NORTH ST	5855	5859	12	38	Alligator	Mill & Overlay	\$7,054.66	22	101.9
785	W 9600 NORTH ST	5861	5899	12	38	Alligator	Mill & Overlay	\$31,575.90	22	456.2
786	W 9600 NORTH ST	5901	5999	12	38	Alligator	Mill & Overlay	\$33,836.15	22	488.9
787	W 9600 NORTH ST	6001	6039	12	38	Alligator	Mill & Overlay	\$28,453.24	34	266.0
788	W 9600 NORTH ST	6041	6149	13	56	Alligator	Thin Overlay	\$7.00	34	694.2
789	W 9600 NORTH ST	6151	6219	13	56	Alligator	Thin Overlay	\$7.00	34	494.8
790	W 9600 NORTH ST	6221	6249	13	56	Alligator	Thin Overlay	\$7.00	37	369.6
791	W 9600 NORTH ST	6251	6299	13	56	Alligator	Thin Overlay	\$7.00	36	204.0
792	W 9600 NORTH ST	6301	6349	13	56	Alligator	Thin Overlay	\$7.00	36	567.1
793	W 9600 NORTH ST	6351	6529	230	19	Alligator	Reconstruct	\$140,970.58	34	637.9
794	W 9600 NORTH ST	6351	6529	230	19	Alligator	Reconstruct	\$72,827.64	34	329.5
795	W 9600 NORTH ST	6531	6559	14	27	Patching	Reconstruct	\$45,003.10	40	173.1
796	W 9600 NORTH ST	6561	6599	14	27	Patching	Reconstruct	\$46,839.93	40	180.2
797	W 9600 NORTH ST	6601	6619	14	27	Patching	Reconstruct	\$75,163.66	40	289.1
798	W 9600 NORTH ST	6621	6669	14	27	Patching	Reconstruct	\$39,983.74	40	153.8
799	W 9600 NORTH ST	6671	6799	14	27	Patching	Reconstruct	\$245,535.74	40	944.4
800	W 9600 NORTH ST	6801	7199	15	6	Pothole	Reconstruct	\$206,657.42	33	963.4
801	W 9600 NORTH ST	6801	7199	15	6	Pothole	Reconstruct	\$69,614.86	42	255.0
802	W 9600 NORTH ST	6801	7199	15	6	Pothole	Reconstruct	\$12,895.97	32	62.0
803	W 9600 NORTH ST	6801	7199	15	6	Pothole	Reconstruct	\$60,839.88	26	360.0
804	W 9620 NORTH ST	5501	5599	229	22	Patching	Reconstruct	\$101,921.09	25	627.2
805	W 9680 NORTH ST	6021	6039	189	49	Alligator	Overlay	\$12,784.10	34	157.1
806	W 9680 NORTH ST	6041	6099	189	49	Alligator	Overlay	\$29,441.72	34	361.7
807	W 9680 NORTH ST	6101	6149	189	49	Alligator	Overlay	\$26,068.00	34	320.3
808	W 9680 NORTH ST	6151	6219	189	49	Alligator	Overlay	\$40,520.18	34	497.9
809	W 9680 NORTH ST	6621	6629	179	48	Depressions	Overlay	\$22,457.53	34	157.1
810	W 9680 NORTH ST	6631	6669	179	48	Depressions	Overlay	\$31,603.33	34	221.0

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
811	W 9700 NORTH ST	5451	5519	10	50	Alligator	Overlay	\$62,434.78	52	374.8
812	W 9700 NORTH ST	5521	5579	10	50	Alligator	Overlay	\$77,177.84	52	463.3
813	W 9720 NORTH ST	6631	6669	179	48	Depressions	Overlay	\$42,157.31	34	294.9
814	W 9740 NORTH ST	6001	6099	188	60	Patching	Chip Seal	\$18,231.35	34	645.2
815	W 9740 NORTH ST	6101	6211	188	60	Patching	Chip Seal	\$22,172.39	34	784.7
816	W 9750 NORTH ST	5651	5739	197	68	Long/Trans	Chip Seal	\$7,931.05	34	237.4
817	W 9750 NORTH ST	5651	5739	196	70	Long/Trans	Chip Seal	\$3,112.27	34	213.4
818	W 9770 NORTH ST	6631	6799	178	86	Pothole	Do Nothing	\$0.00	34	683.8
819	W 9770 NORTH ST	6631	6799	177	75	Block	Chip Seal	\$3,291.64	34	469.6
820	W 9800 NORTH ST	5581	5649	10	50	Alligator	Chip Seal	\$89,071.27	52	534.7
821	W 9800 NORTH ST	5651	5799	10	50	Alligator	Overlay	\$187,851.84	52	1127.7
822	W 9800 NORTH ST	6001	6019	187	78	Weathering	Slurry Seal	\$5,199.58	34	188.4
823	W 9800 NORTH ST	6021	6079	187	78	Weathering	Slurry Seal	\$8,983.23	34	325.6
824	W 9800 NORTH ST	6081	6099	187	78	Weathering	Slurry Seal	\$3,046.82	34	110.4
825	W 9800 NORTH ST	6101	6129	187	78	Weathering	Slurry Seal	\$5,836.10	34	211.5
826	W 9800 NORTH ST	6131	6179	187	78	Weathering	Slurry Seal	\$11,975.02	34	434.0
827	W 9800 NORTH ST	6801	6819	175	75	Weathering	Slurry Seal	\$17,815.73	34	198.1
828	W 9800 NORTH ST	6821	6849	175	75	Weathering	Slurry Seal	\$14,123.24	34	157.1
829	W 9810 NORTH ST	6531	6629	184	78	Block	Slurry Seal	\$2,048.32	34	399.6
830	W 9810 NORTH ST	6531	6629	177	75	Block	Chip Seal	\$1,306.93	34	186.4
831	W 9850 NORTH ST	5801	5873	10	50	Alligator	Overlay	\$86,458.24	52	519.0
832	W 9850 NORTH ST	5875	5933	10	50	Alligator	Overlay	\$63,626.43	52	382.0
833	W 9850 NORTH ST	5935	5999	10	50	Alligator	Overlay	\$74,417.48	52	446.7
834	W 9860 NORTH ST	6001	6039	11	70	Long/Trans	Chip Seal	\$6,292.73	52	288.6
835	W 9860 NORTH ST	6041	6109	11	70	Long/Trans	Chip Seal	\$9,397.88	52	431.0
836	W 9860 NORTH ST	6111	6179	11	70	Long/Trans	Chip Seal	\$5,560.82	52	464.5
837	W 9860 NORTH ST	6181	6249	11	70	Long/Trans	Chip Seal	\$10,129.58	52	255.0
838	W 9860 NORTH ST	6181	6249	11	70	Long/Trans	Chip Seal	\$5,560.82	52	255.0
839	W 9860 NORTH ST	6251	6319	11	70	Long/Trans	Chip Seal	\$3,259.51	38	204.5
840	W 9860 NORTH ST	6321	6369	11	70	Long/Trans	Chip Seal	\$7,001.67	38	439.4
841	W 9860 NORTH ST	6371	6399	11	70	Long/Trans	Chip Seal	\$3,592.79	38	225.5
842	W 9890 NORTH ST	6361	6363	186	78	Long/Trans	Chip Seal	\$6,103.13	38	383.0
843	W 9890 NORTH ST	6365	6399	186	78	Long/Trans	Slurry Seal	\$505.71	34	144.9
844	W 9900 NORTH ST	6801	6899	175	75	Weathering	Slurry Seal	\$548.40	34	157.1
845	W 9910 NORTH ST	5321	5399	200	90	Long/Trans	Slurry Seal	\$28,949.17	34	322.0
846	W 9910 NORTH ST	5401	5479	200	90	Long/Trans	Slurry Seal	\$1,577.84	34	439.6
847	W 9960 NORTH ST	6371	6373	186	78	Long/Trans	Slurry Seal	\$1,041.18	34	290.1
848	W 9960 NORTH ST	6375	6399	186	78	Long/Trans	Slurry Seal	\$518.38	34	148.5
849	W 9970 NORTH ST	5741	5799	202	80	Long/Trans	Slurry Seal	\$548.40	34	157.1
850	W 9975 NORTH ST	6801	6819	175	75	Weathering	Slurry Seal	\$1,302.96	34	364.0
851	W 9975 NORTH ST	6821	6839	175	75	Weathering	Slurry Seal	\$12,152.86	34	135.2
852	W ADONIS DR	6221	6379	109	68	Weathering	Slurry Seal	\$14,123.21	34	157.1
853	W ANSLEY CIR	6875	6889	161	46	Long/Trans	Chip Seal	\$70,658.30	34	1073.6
854	W ANSLEY CIR	6891	6899	161	46	Alligator	Chip Seal	\$7,443.38	34	157.1
855	W ALPINE CIR	4941	5009	215	73	Alligator	Chip Seal	\$3,485.03	34	73.5
						Block	Chip Seal	\$21,892.00	34	880.8

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
856	W ANDREW DR	5731	5829	9	42	Block	Mill & Overlay	\$125,600.49	34	657.7
857	W ANDREW DR	5731	5829	9	42	Block	Mill & Overlay	\$24,185.02	34	126.6
858	W APOLLO WAY	6151	6189	108	34	Depressions	Reconstruct	\$42,716.21	34	193.3
859	W APOLLO WAY	6191	6259	108	34	Depressions	Reconstruct	\$108,304.27	34	490.1
860	W APOLLO WAY	6261	6279	108	34	Depressions	Reconstruct	\$43,140.12	34	195.2
861	W ARGO CIR	6151	6249	108	34	Depressions	Reconstruct	\$174,799.05	34	790.9
862	W ASPEN HOLLOW CIR	6761	6799	181	90	Weathering	Slurry Seal	\$630.17	34	184.4
863	W AVERY AVE	6481	6569	159	78	Weathering	Slurry Seal	\$1,575.20	34	462.0
864	W AVERY AVE	6571	6609	159	78	Weathering	Slurry Seal	\$1,650.93	34	484.2
865	W AVERY AVE	6611	6709	159	78	Weathering	Slurry Seal	\$2,858.43	34	838.3
866	W AVERY CIR	6845	6849	161	46	Alligator	Chip Seal	\$7,443.41	34	157.1
867	W AVERY CIR	6851	6869	161	46	Alligator	Chip Seal	\$5,365.50	34	113.2
868	W AVONMORE CIR	5821	5849	136	78	Weathering	Slurry Seal	\$681.05	42	157.1
869	W AVONMORE CIR	5851	5899	136	78	Weathering	Slurry Seal	\$1,059.08	42	244.3
870	W BEACON HILL BLVD	5831	5959	44	40	Patching	Mill & Overlay	\$113,318.63	34	771.1
871	W BRADEN ST	5621	5679	203	99	Patching	Do Nothing	\$0.00	30	297.5
872	W BROADLEAF HOLLOW LN	6651	6699	112	80	Weathering	Slurry Seal	\$968.89	34	280.8
873	W BROADLEAF HOLLOW LN	6701	6799	112	80	Weathering	Slurry Seal	\$1,685.41	34	488.4
874	W BROOKRIDGE LN	4615	4649	213	90	Depressions	Do Nothing	\$0.00	34	157.1
875	W BROOKRIDGE LN	4651	4689	213	90	Depressions	Do Nothing	\$0.00	34	578.9
876	W BULL RIVER RD	6001	6029	115	62	Depressions	Slurry Seal	\$7,038.57	34	228.2
877	W BULL RIVER RD	6031	6089	115	62	Depressions	Slurry Seal	\$10,912.79	34	353.8
878	W BULL RIVER RD	6091	6129	115	62	Depressions	Slurry Seal	\$9,583.33	34	310.7
879	W BULL RIVER RD	6131	6179	115	62	Depressions	Slurry Seal	\$10,457.95	34	339.1
880	W BULL RIVER RD	6181	6309	114	58	Patching	Chip Seal	\$53,375.56	34	659.5
881	W BULL RIVER RD	6181	6309	115	62	Depressions	Slurry Seal	\$6,216.64	34	201.6
882	W BULL RIVER RD	6311	6439	114	58	Patching	Chip Seal	\$59,488.80	34	735.0
883	W BULL RIVER RD	6311	6439	113	78	Weathering	Slurry Seal	\$806.98	34	229.9
884	W BULL RIVER RD	6441	6523	113	78	Weathering	Slurry Seal	\$3,621.23	34	1031.7
885	W BULL RIVER RD	6525	6599	113	78	Weathering	Slurry Seal	\$2,637.84	34	751.5
886	W BULL RIVER RD	6601	6629	111	75	Patching	Chip Seal	\$14,965.94	34	341.8
887	W BURGUNDY CT	6601	6609	118	90	Weathering	Slurry Seal	\$808.33	34	235.6
888	W BURGUNDY CT	6611	6633	118	90	Weathering	Slurry Seal	\$538.94	34	157.1
889	W CADDIE LN	0	0	214	90	Weathering	Slurry Seal	\$790.80	20	393.8
890	W CADDIE LN	0	0	214	90	Weathering	Slurry Seal	\$3,122.58	20	1554.8
891	W CADDIE LN	0	0	214	90	Weathering	Slurry Seal	\$985.80	20	490.8
892	W CADDIE LN	4421	4439	214	90	Weathering	Slurry Seal	\$315.47	20	157.1
893	W CADDIE LN	4441	4499	214	90	Weathering	Slurry Seal	\$811.97	20	404.3
894	W CADDIE LN	4501	4729	214	90	Weathering	Slurry Seal	\$3,122.31	20	1554.7
895	W CADDIE LN	4731	4799	214	90	Weathering	Slurry Seal	\$987.43	20	491.7
896	W CANTERBURY CIR	6855	6889	161	46	Alligator	Chip Seal	\$8,333.14	34	175.9
897	W CANTERBURY CIR	6891	6893	161	46	Alligator	Chip Seal	\$7,443.44	34	157.1
898	W CANTERBURY CT	6691	6709	160	49	Weathering	Overlay	\$17,924.94	34	157.1
899	W CANTERBURY CT	6711	6743	160	49	Weathering	Overlay	\$35,693.96	34	312.8
900	W CANTERBURY CT	6745	6769	160	49	Weathering	Overlay	\$16,929.10	34	148.4

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
901	W CANTERBURY CT	6771	6779	160	49	Weathering	Overlay	\$17,924.88	34	157.1
902	W CANTERBURY DR	6601	6683	159	78	Weathering	Slurry Seal	\$2,034.69	34	596.7
903	W CANTERBURY DR	6685	6793	159	78	Weathering	Slurry Seal	\$3,228.80	34	946.9
904	W CANTERBURY LN	6701	6799	160	49	Weathering	Overlay	\$89,270.25	34	782.3
905	W CANTERBURY PARK CIR	5921	5999	192	68	Long/Trans	Chip Seal	\$15,091.02	34	441.6
906	W CANTERBURY PARK CIR N	5845	5919	192	68	Long/Trans	Chip Seal	\$14,331.75	34	419.3
907	W CANTERBURY PARK CIR S	5871	5919	192	68	Long/Trans	Chip Seal	\$10,227.53	34	299.3
908	W CANTERBURY WAY	6581	6589	160	49	Weathering	Overlay	\$17,925.07	34	157.1
909	W CANTERBURY WAY	6591	6599	160	49	Weathering	Overlay	\$10,550.38	34	92.5
910	W CANTERBURY WAY	6601	6749	160	49	Weathering	Overlay	\$110,053.07	34	964.4
911	W CANTERBURY WAY	6751	6779	160	49	Weathering	Overlay	\$35,313.52	34	309.5
912	W CANTERBURY WAY	6781	6799	160	49	Weathering	Overlay	\$17,179.16	34	150.5
913	W CANNON VIEW DR	4651	4799	220	58	Block	Overlay	\$76,386.91	34	1123.3
914	W CARSON DR	5671	5769	148	90	Weathering	Slurry Seal	\$1,511.47	34	444.6
915	W CASTLE PINE DR	5201	5213	216	80	Depressions	Do Nothing	\$0.00	34	172.9
916	W CASTLE PINE DR	5215	5249	216	80	Depressions	Do Nothing	\$0.00	34	157.1
917	W CASTLE PINE WAY	5191	5249	216	80	Depressions	Do Nothing	\$0.00	34	418.9
918	W CENTURY HEIGHTS DR	5831	5929	103	72	Long/Trans	Chip Seal	\$57,904.31	34	639.6
919	W CHAMBERRY WAY	6001	6049	106	70	Long/Trans	Chip Seal	\$11,568.95	34	179.1
920	W CHAMBERRY WAY	6051	6099	106	70	Long/Trans	Chip Seal	\$19,237.76	34	297.8
921	W CHAPEL DR	6001	6119	154	80	Weathering	Slurry Seal	\$2,643.50	34	774.2
922	W CHAPEL DR	6121	6149	154	80	Weathering	Slurry Seal	\$970.96	34	284.4
923	W GHATHAM CIR	5935	5943	100	86	Weathering	Slurry Seal	\$535.60	34	157.1
924	W GHATHAM CIR	5945	5949	100	86	Weathering	Slurry Seal	\$670.82	34	196.7
925	W CIVIC CENTER DR	5401	5499	144	60	Pothole	Mill & Overlay	\$39,385.98	34	352.8
926	W COMPTON WAY	5675	5729	148	90	Weathering	Slurry Seal	\$1,121.42	34	329.8
927	W COMPTON WAY	5731	5749	148	90	Weathering	Slurry Seal	\$844.73	34	248.4
928	W CONNOR CT	5775	5789	120	48	Block	Overlay	\$16,581.23	34	157.1
929	W CONNOR CT	5791	5829	120	48	Block	Overlay	\$36,321.19	34	344.1
930	W CORAL CV	5931	5939	102	86	Weathering	Slurry Seal	\$536.30	34	157.1
931	W CORAL CV	5941	5959	102	86	Weathering	Slurry Seal	\$252.31	34	73.9
932	W CORAL CV	0	0	219	62	Block	Chip Seal	\$460.05	34	60.8
933	W COUNTRY CLUB DR	4601	4649	220	58	Block	Overlay	\$22,169.83	34	326.0
934	W COUNTRY CLUB DR	4651	4799	220	58	Block	Overlay	\$74,760.78	34	1099.4
935	W COUNTRY CLUB DR	4801	4849	219	62	Block	Chip Seal	\$2,845.66	34	376.2
936	W COUNTRY CLUB DR	4851	4913	219	62	Block	Chip Seal	\$3,718.61	34	491.6
937	W COUNTRY CLUB DR	4915	5009	215	73	Block	Chip Seal	\$22,735.94	37	840.5
938	W COUNTRY CLUB DR	5011	5109	215	73	Block	Chip Seal	\$23,921.31	37	884.4
939	W COUNTRY CLUB DR	5111	5129	215	73	Block	Chip Seal	\$3,093.63	34	124.5
940	W COUNTRY CLUB DR	5131	5189	215	73	Block	Chip Seal	\$10,599.44	34	426.4
941	W COUNTRY CLUB DR	5191	5249	217	40	Pothole	Reconstruct	\$121,249.31	34	548.6
942	W COUNTRY CLUB DR	5251	5269	217	40	Pothole	Reconstruct	\$47,029.65	34	212.8
943	W COVENTRY RD	5491	5599	145	86	Weathering	Slurry Seal	\$2,158.06	28	752.6
944	W DAYS CIR	6111	6113	154	80	Weathering	Slurry Seal	\$536.37	34	157.1
945	W DAYS CIR	6115	6139	154	80	Weathering	Slurry Seal	\$550.58	34	161.2

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
946	W DEER HOLLOW WAY	6481	6569	159	78	Weathering	Slurry Seal	\$1,463.78	34	429.3
947	W DIAMOND CIR	6241	6249	189	49	Alligator	Overlay	\$12,958.39	34	159.2
948	W DIAMOND CIR	6251	6259	189	49	Alligator	Overlay	\$12,784.26	34	157.1
949	W DRY CREEK CIR	6031	6049	116	58	Pothole	Mill & Overlay	\$19,136.77	34	157.1
950	W DRY CREEK CIR	6051	6129	116	58	Pothole	Mill & Overlay	\$70,167.30	34	575.9
951	W DRY CREEK CIR	6151	6179	116	58	Pothole	Mill & Overlay	\$55,196.90	34	453.1
952	W DRY CREEK CIR	6181	6199	116	58	Pothole	Mill & Overlay	\$19,136.99	34	157.1
953	W DRY CREEK RD	6001	6103	116	58	Pothole	Mill & Overlay	\$95,683.05	34	785.4
954	W DRY CREEK RD	6105	6159	116	58	Pothole	Mill & Overlay	\$42,880.92	34	352.0
955	W DRY CREEK RD	6161	6225	116	58	Pothole	Mill & Overlay	\$19,137.11	34	157.1
956	W EARL PL	0	0	209	80	Pothole	Do Nothing	\$0.00	34	190.1
957	W EARL PL	5201	5299	209	80	Pothole	Do Nothing	\$0.00	34	444.2
958	W EARL PL	5301	5399	209	80	Pothole	Do Nothing	\$0.00	34	509.2
959	W EAST PANORAMA DR	4729	4799	220	58	Block	Do Nothing	\$33,927.74	34	498.9
960	W ELK COVE CIR	4185	4203	221	86	Weathering	Slurry Seal	\$544.88	34	157.1
961	W ELK COVE CIR	4205	4243	221	86	Weathering	Slurry Seal	\$983.49	34	283.5
962	W EVERGREEN CIR	5351	5359	125	50	Depressions	Overlay	\$14,817.59	34	157.1
963	W EVERGREEN CIR	5361	5369	125	50	Depressions	Overlay	\$33,446.62	34	354.6
964	W EVERGREEN WAY	5371	5379	125	50	Depressions	Overlay	\$19,997.80	34	212.0
965	W FOOTHILL DR	6001	6099	110	54	Patching	Mill & Overlay	\$88,936.60	34	565.2
966	W HAMPTON CT	5191	5209	217	40	Pothole	Reconstruct	\$37,028.82	25	227.9
967	W HAMPTON CT	5211	5223	217	40	Pothole	Reconstruct	\$25,525.68	25	157.1
968	W HIDDEN DR	5401	5589	200	90	Long/Trans	Slurry Seal	\$1,495.18	34	416.5
969	W HIDDEN MEADOW DR	5951	6149	100	86	Weathering	Slurry Seal	\$1,401.79	34	411.1
970	W HIDDEN MEADOW DR	5951	6149	100	86	Weathering	Slurry Seal	\$6,236.26	34	227.9
971	W HIDDEN POND DR	6151	6199	100	86	Weathering	Slurry Seal	\$743.11	34	217.9
972	W HIDDEN POND DR	6301	6399	171	32	Weathering	Reconstruct	\$160,730.06	34	727.3
973	W HORIZON DR	5875	5929	105	80	Weathering	Slurry Seal	\$1,036.93	34	303.5
974	W HORIZON DR	5931	5979	105	80	Weathering	Slurry Seal	\$961.63	34	281.4
975	W HY LAND ACRES	5265	5369	146	68	Long/Trans	Chip Seal	\$2,069.42	34	312.1
976	W IVERSON CIR	7025	7029	162	90	Patching	Slurry Seal	\$543.00	34	157.1
977	W IVERSON CIR	7031	7049	162	90	Patching	Slurry Seal	\$500.38	34	144.7
978	W JERLING CIR	5081	5089	215	73	Block	Chip Seal	\$3,586.80	34	144.3
979	W JERLING CIR	5091	5099	215	73	Block	Chip Seal	\$3,904.40	34	157.1
980	W JOEY CT	4825	4849	126	80	Long/Trans	Slurry Seal	\$591.04	34	157.1
981	W JOEY CT	4831	4879	126	80	Long/Trans	Slurry Seal	\$1,019.17	34	270.9
982	W JONATHAN RD	4881	4879	126	80	Long/Trans	Slurry Seal	\$1,930.85	34	513.1
983	W JONATHAN RD	4881	4899	126	80	Long/Trans	Slurry Seal	\$860.29	34	228.6
984	W JULIE ANN PL	5301	5313	209	80	Pothole	Do Nothing	\$0.00	34	365.2
985	W JULIE ANN PL	5315	5349	209	80	Pothole	Do Nothing	\$0.00	34	157.1
986	W KADEN ST	5621	5679	203	99	Patching	Do Nothing	\$0.00	30	300.1
987	W KAITLYN CIR	5775	5789	120	48	Block	Overlay	\$16,581.26	34	157.1
988	W KAITLYN CIR	5791	5829	120	48	Block	Overlay	\$26,076.06	34	247.0
989	W KAITLYN LN	6645	6649	137	49	Depressions	Overlay	\$25,937.60	34	253.3
990	W KAITLYN LN	6651	6675	137	49	Depressions	Overlay	\$16,082.36	34	157.1

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
991	W KENSINGTON CIR	5485	5549	201	90	Patching	Slurry Seal	\$1,736.01	30	560.4
992	W KENSINGTON CIR	5551	5569	201	90	Patching	Slurry Seal	\$486.63	30	157.1
993	W LAUSANNE ST	6051	6149	106	70	Long/Trans	Chip Seal	\$39,596.43	34	613.0
994	W LAUSANNE ST	6051	6149	107	50	Weathering	Overlay	\$15,797.92	34	115.8
995	W LIGHT HOUSE LANDING	5901	5919	102	86	Weathering	Slurry Seal	\$536.30	34	157.1
996	W LIGHT HOUSE LANDING	5921	5959	102	86	Weathering	Slurry Seal	\$1,147.25	34	336.0
997	W LONE ROCK RD	6211	6309	114	58	Patching	Chip Seal	\$51,864.76	34	640.8
998	W LONE ROCK RD	6311	6389	114	58	Patching	Chip Seal	\$33,280.47	34	411.2
999	W LONE ROCK RD	6391	6439	113	78	Weathering	Slurry Seal	\$1,000.56	34	285.1
1000	W LONE ROCK RD	6391	6439	114	58	Patching	Chip Seal	\$11,299.13	34	139.6
1001	W LONE ROCK RD	6441	6499	113	78	Weathering	Slurry Seal	\$1,691.31	34	481.9
1002	W MADIE LN	5751	5799	148	90	Weathering	Slurry Seal	\$1,041.25	34	306.2
1003	W MADISON AVE	6601	6629	176	70	Pothole	Mill & Overlay	\$32,858.83	34	253.3
1004	W MADISON AVE	6631	6669	176	70	Pothole	Mill & Overlay	\$40,920.98	34	315.4
1005	W MADISON AVE	6671	6689	176	70	Pothole	Mill & Overlay	\$29,715.62	34	229.0
1006	W MADISON AVE	6691	6799	176	70	Pothole	Mill & Overlay	\$84,839.04	34	653.9
1007	W MARIE JOHNSON CIR	6791	6799	160	49	Weathering	Overlay	\$17,924.71	34	157.1
1008	W MARIE JOHNSON CIR	6801	6815	160	49	Weathering	Overlay	\$18,488.48	34	162.0
1009	W MEADOWS DR	5531	5559	227	78	Long/Trans	Slurry Seal	\$3,146.51	52	356.6
1010	W MEADOWS DR	5551	5599	227	78	Long/Trans	Slurry Seal	\$2,920.89	52	331.0
1011	W MOUNTAIN VIEW CIR	4831	4923	219	62	Block	Chip Seal	\$6,626.59	34	876.1
1012	W NATALIE LN	5601	5619	203	99	Patching	Do Nothing	\$0.00	30	185.9
1013	W NEW LONDON ST	5945	5949	100	86	Weathering	Slurry Seal	\$535.60	34	157.1
1014	W NEW LONDON ST	5951	5999	100	86	Weathering	Slurry Seal	\$675.45	34	198.1
1015	W NEW LONDON ST	6001	6149	100	86	Weathering	Slurry Seal	\$1,224.21	34	359.0
1016	W NORMANDY WAY	6561	6619	118	90	Weathering	Slurry Seal	\$1,714.73	34	499.8
1017	W NORMANDY WAY	6621	6679	118	90	Weathering	Slurry Seal	\$1,790.99	34	522.0
1018	W NORMANDY WAY	6679	6679	118	90	Weathering	Slurry Seal	\$1,146.86	34	625.7
1019	W NORMANDY WAY	6681	6729	118	90	Weathering	Slurry Seal	\$1,450.74	34	422.8
1020	W NORMANDY WAY	6731	6799	118	90	Weathering	Slurry Seal	\$1,573.37	34	458.6
1021	W NORTH JERLING DR	5091	5159	215	73	Block	Chip Seal	\$13,294.54	34	534.9
1022	W NORTH STAR DR	5881	5929	105	80	Weathering	Slurry Seal	\$723.26	34	211.7
1023	W NORTH STAR DR	5931	5983	105	80	Weathering	Slurry Seal	\$1,304.62	34	381.8
1024	W OLE BISH LN	4721	4799	212	70	Long/Trans	Chip Seal	\$6,457.84	34	492.1
1025	W PANORAMA DR	4801	4829	219	62	Block	Chip Seal	\$2,034.31	34	268.9
1026	W PANORAMA DR	4831	4949	219	62	Block	Chip Seal	\$6,083.71	34	804.3
1027	W PARK CIR	4031	4109	221	86	Weathering	Slurry Seal	\$3,092.01	34	891.4
1028	W PARK DR	4061	4159	221	86	Weathering	Slurry Seal	\$2,059.88	34	593.8
1029	W PARK DR	4161	4243	221	86	Weathering	Slurry Seal	\$3,057.31	34	881.4
1030	W PARK WEST RD	5811	5899	103	72	Long/Trans	Chip Seal	\$46,976.23	34	518.9
1031	W PARK WEST RD	5901	5939	103	72	Long/Trans	Chip Seal	\$53,979.01	34	596.3
1032	W PARKWAY EAST ST	5251	5399	144	60	Pothole	Mill & Overlay	\$48,087.95	34	430.7
1033	W PARKWAY WEST	5491	5599	144	60	Pothole	Mill & Overlay	\$83,634.73	34	749.1
1034	W PEBBLE LN	5391	5409	199	90	Weathering	Slurry Seal	\$534.07	34	157.1
1035	W PEBBLE LN	5411	5449	199	90	Weathering	Slurry Seal	\$1,220.74	34	359.0

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
1036	W RED HAWK DR	7031	7069	162	90	Patching	Slurry Seal	\$885.96	34	256.3
1037	W RED HAWK DR	7071	7149	162	90	Patching	Slurry Seal	\$2,271.45	34	657.1
1038	W RED HAWK DR	7151	7199	162	90	Patching	Slurry Seal	\$1,357.27	34	392.6
1039	W REISNER DR	6001	6149	139	42	Alligator	Mill & Overlay	\$114,856.19	34	954.4
1040	W RIDGE RD	6001	6089	115	62	Depressions	Slurry Seal	\$19,169.91	34	621.5
1041	W RIDGE RD	6091	6199	115	62	Depressions	Slurry Seal	\$23,010.60	34	746.1
1042	W RIDGE RD	6091	6199	114	58	Patching	Chip Seal	\$7,268.32	34	89.8
1043	W RIDGE RD	6201	6209	114	58	Patching	Chip Seal	\$12,648.76	34	156.3
1044	W RIDGE RD	6211	6289	114	58	Patching	Chip Seal	\$58,916.85	34	727.9
1045	W SAMPSON CT	4825	4839	126	80	Long/Trans	Slurry Seal	\$591.11	34	157.1
1046	W SAMPSON CT	4841	4879	126	80	Long/Trans	Slurry Seal	\$973.73	34	258.8
1047	W SCHOOL PARK DR	5251	5299	208	78	Block	Slurry Seal	\$1,470.91	42	281.1
1048	W SCHOOL PARK DR	5301	5399	208	78	Block	Slurry Seal	\$1,736.76	34	410.0
1049	W SEGO LILY CT	4735	4749	213	90	Depressions	Do Nothing	\$0.00	34	241.7
1050	W SEGO LILY CT	4751	4773	213	90	Depressions	Do Nothing	\$0.00	34	157.1
1051	W SHEPHERDS PATH RD	5831	5933	103	72	Long/Trans	Chip Seal	\$32,623.99	34	360.4
1052	W SHORELINE DR	4021	4059	221	86	Weathering	Slurry Seal	\$1,533.91	34	442.2
1053	W SKY LINE DR	6311	6389	114	58	Patching	Chip Seal	\$37,771.55	34	466.7
1054	W SKY LINE DR N	6201	6309	114	58	Patching	Chip Seal	\$59,380.99	34	733.7
1055	W SKY LINE DR N	6311	6389	114	58	Patching	Chip Seal	\$37,692.89	34	465.7
1056	W SOUTHERN CROSS CT	5941	5949	105	80	Weathering	Slurry Seal	\$536.70	34	157.1
1057	W SOUTHERN CROSS CT	5951	5979	105	80	Weathering	Slurry Seal	\$496.08	34	145.2
1058	W SPRING HOLLOW LN	6701	6799	112	80	Weathering	Slurry Seal	\$1,547.76	34	448.5
1059	W SPRUCE CT	4401	4419	129	90	Pothole	Do Nothing	\$0.00	34	157.0
1060	W STEVENS LN	4421	4499	129	90	Pothole	Do Nothing	\$0.00	34	464.5
1061	W STEVENS LN	6401	6529	137	49	Depressions	Overlay	\$110,760.75	34	1081.8
1062	W STEVENS LN	6531	6629	137	49	Depressions	Overlay	\$98,808.18	34	965.1
1063	W STONE CREEK CIR	5325	5329	125	50	Depressions	Overlay	\$14,817.50	34	157.1
1064	W STONE CREEK CIR	5331	5369	125	50	Depressions	Overlay	\$36,145.11	34	383.2
1065	W STONE CREEK DR	5371	5449	124	70	Weathering	Chip Seal	\$5,343.69	34	280.9
1066	W STONE CREEK DR	5451	5499	124	70	Weathering	Chip Seal	\$7,795.76	34	409.8
1067	W SUNRISE DR	6101	6159	110	54	Patching	Mill & Overlay	\$69,520.62	34	441.8
1068	W SUNRISE DR	6161	6199	110	54	Patching	Mill & Overlay	\$40,423.56	34	256.9
1069	W SUNSET HILLS CT	6621	6639	111	75	Patching	Chip Seal	\$8,969.36	34	204.8
1070	W SUNSET HILLS CT	6641	6649	111	75	Patching	Chip Seal	\$6,877.97	34	157.1
1071	W SUNSET HILLS DR	6601	6649	113	78	Weathering	Slurry Seal	\$1,189.76	34	339.0
1072	W THORNTON CIR	6161	6169	193	80	Weathering	Slurry Seal	\$285.24	34	83.8
1073	W THORNTON CIR	6171	6199	193	80	Weathering	Slurry Seal	\$534.41	34	157.1
1074	W THORNTON LN	6001	6159	193	80	Weathering	Slurry Seal	\$3,107.51	27	1150.2
1075	W TIMBER RIDGE LN	5841	5899	101	70	Long/Trans	Chip Seal	\$6,650.01	34	243.0
1076	W TIMBER RIDGE LN	5901	5949	101	70	Long/Trans	Chip Seal	\$11,029.11	34	403.1
1077	W TOWN CENTER PKWY	5251	5319	227	78	Long/Trans	Slurry Seal	\$2,614.70	52	296.3
1078	W TOWN CENTER PKWY	5321	5399	227	78	Long/Trans	Slurry Seal	\$4,140.61	52	469.3
1079	W TOWN CENTER PKWY	5401	5489	227	78	Long/Trans	Slurry Seal	\$2,986.51	52	338.5
1080	W TREASURE CV	5911	5919	102	86	Weathering	Slurry Seal	\$536.30	34	157.1

MAP ID	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
1081	W TREASURE CV	5921	5959	102	86	Weathering	Slurry Seal	\$825.00	34	241.6
1082	W VALLEY VIEW DR	6015	6039	110	54	Patching	Mill & Overlay	\$24,717.37	34	157.1
1083	W VALLEY VIEW DR	6041	6099	110	54	Patching	Mill & Overlay	\$77,878.91	34	494.9
1084	W VALLEY VIEW DR	6101	6149	110	54	Patching	Mill & Overlay	\$45,529.41	34	289.3
1085	W VALLEY VIEW DR	6151	6199	110	54	Patching	Mill & Overlay	\$50,509.51	34	321.0
1086	W VICTORIA LN	5801	5949	152	90	Pothole	Do Nothing	\$0.00	34	673.7
1087	W VIEW POINTE DR	4061	4159	221	86	Weathering	Slurry Seal	\$2,386.12	34	687.9
1088	W VINTAGE LN	6631	6799	178	86	Pothole	Do Nothing	\$0.00	34	689.8
1089	W VINTAGE LN	6631	6799	177	75	Block	Chip Seal	\$3,266.92	34	466.1
1090	W VISTA DR	4651	4799	220	58	Block	Overlay	\$75,472.88	34	1109.9
1091	W WASATCH DR	4675	4729	220	58	Block	Overlay	\$19,116.67	34	281.1
1092	W WASATCH DR	4731	4799	220	58	Block	Overlay	\$33,313.41	34	489.9
1093	W WESTFIELD CV	5801	5829	104	86	Weathering	Slurry Seal	\$810.04	34	237.6
1094	W WESTFIELD RD	1061	1069	104	86	Weathering	Slurry Seal	\$421.64	34	123.7
1095	W WESTFIELD RD	1071	1085	104	86	Weathering	Slurry Seal	\$1,551.93	34	455.1
1096	W WESTFIELD RD	5851	5899	104	86	Patching	Chip Seal	\$3,209.75	38	189.2
1097	W WESTFIELD RD	5901	5929	4	75	Patching	Chip Seal	\$9,020.07	38	531.6
1098	W WESTFIELD RD	5931	5999	4	75	Patching	Chip Seal	\$7,594.56	38	447.6
1099	W WILDFLOWER CT	5891	5893	101	70	Long/Trans	Chip Seal	\$4,297.83	34	157.1
1100	W WILDFLOWER CT	5885	5909	101	70	Long/Trans	Chip Seal	\$2,358.33	34	86.2
1101	W WILDFLOWER LN	5831	5949	101	70	Long/Trans	Chip Seal	\$9,918.86	34	362.5
1102	W WILLEM PL	5345	5349	208	78	Block	Slurry Seal	\$880.18	34	207.8
1103	W WILLEM PL	5351	5373	208	78	Block	Slurry Seal	\$665.43	34	157.1
1104	W WINDSOR LN	5255	5269	217	40	Pothole	Reconstruct	\$25,525.30	25	157.1
1105	W WINDSOR LN	5271	5279	217	40	Pothole	Reconstruct	\$49,307.98	25	303.4
1106	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$230.36	34	65.6
1107	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$219.38	34	62.5
1108	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$208.18	34	59.3
1109	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$207.18	34	59.0
1110	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$295.39	34	84.1
1111	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$201.75	34	57.5
1112	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$194.10	34	55.3
1113	W WINDSOR PARK DR	0	0	201	90	Patching	Slurry Seal	\$163.00	34	46.4
1114	W WINDSOR PARK DR	5431	5479	201	90	Patching	Slurry Seal	\$867.83	34	247.2
1115	W WINDSOR PARK DR	5481	5549	201	90	Patching	Slurry Seal	\$1,969.06	34	560.8
1116	W WINDSOR PARK DR	5551	5599	201	90	Patching	Slurry Seal	\$1,460.11	34	415.9
1117	W WINDSOR PARK DR	5601	5629	201	90	Patching	Slurry Seal	\$686.82	34	195.6
1118	W WINDSOR PARK DR	5631	5679	201	90	Patching	Slurry Seal	\$1,175.28	34	334.7
1119	W WINDSOR PARK DR	5681	5739	201	90	Patching	Slurry Seal	\$925.33	34	263.5
1120	W WINDSOR PARK DR	5681	5739	201	80	Long/Trans	Slurry Seal	\$664.90	34	185.7
1121	W WING PL	5301	5319	209	80	Pothole	Do Nothing	\$0.00	34	309.2
1122	W WING PL	5321	5359	209	80	Pothole	Do Nothing	\$0.00	34	157.1
1123	W WOOD DUCK LN	7001	7029	162	90	Patching	Slurry Seal	\$880.98	34	254.8
1124	W WOODLAND DR	5345	5379	125	50	Depressions	Overlay	\$65,466.69	34	694.0
1125	W WOODS HOLLOW LN	6611	6699	111	75	Patching	Chip Seal	\$20,168.28	34	460.6

0.525

MAP ID NUMBER	STREET NAME	ADDRESS FROM	ADDRESS TO	Zone	PCI	GOVERNING DISTRESS	RECOMMENDED TREATMENT	ESTIMATED COST	WIDTH	LENGTH
1126	W WOODSHIRE LN	5801	5939	152	90	Pothole	Do Nothing	\$0.00	34	639.7
1127	W WOODSHIRE LN	5941	5999	152	90	Pothole	Do Nothing	\$0.00	34	540.3
1128		0	0	210	100	None	Do Nothing	\$0.00	25	750.7
1129		0	0	236	58	Long/Trans	Overlay	\$77,247.85	34	1136.0
1130		0	0	236	58	Long/Trans	Overlay	\$36,923.93	17	1086.0
1131				222	70	Bumps	Slurry Seal	\$9,135.73	20	240.8
1132				222	70	Bumps	Slurry Seal	\$44,651.29	20	1177.1
1133				222	70	Bumps	Slurry Seal	\$4,507.75	20	118.8
1134				222	70	Bumps	Slurry Seal	\$18,880.71	20	497.7
1135				222	70	Bumps	Slurry Seal	\$17,035.70	20	449.1
1136		10031	10099	203	99	Patching	Do Nothing	\$0.00	30	397.7