

WORKING TO MAKE A DIFFERENCE

An employer who fails to comply with the Occupational Health & Safety Regulation or Board orders or directions is subject to sanctions as prescribed in the Workers Compensation Act.

Occupational Health & Safety Regulation requires that one copy of this report remain posted in a conspicuous place at or near the operation inspected for at least seven days, or until compliance has been achieved, whichever is the longer period.

An affected employer, worker, owner, supplier, union or member of a deceased worker's family may, within 90 calendar days of this report, in writing, request the Review Division of the WCB to conduct a review of an order, or the non-issuance of an order, in this report by contacting the Review Division at the Board's Richmond Office. The time limit may be extended in certain circumstances. Employers requiring assistance can contact the Employers' Advisers at 1-800-925-2233 --workers can contact the Workers' Advisers at 1-800-663-4261.

Date of Issue	Number	Number of Orders	Employer	Location	Classification Unit Number	Activity Time Recorded*	Travel Time Recorded*
2007-01-31	2007115520007	0	4000	002	841102	2.75	0.50

\* The Time Recorded reflects only that time which has been charged to this inspection up until the document was printed for delivery. Subsequent time may be added for additional activity related to this inspection.

Number of Workers	Project Number	Site Visit Date	Lab Samples Taken	Direct Readings	Results Presented	Sampling Inspection(s)
51-100			N	N	N	

Head Office	Job Site
PROVINCIAL GOVERNMENT WORKERS' COMPENSATION PROGRAMS BC PUBLIC SERVICE AGENCY P O BOX 9404 STN PROV GOV'T VICTORIA BC V8W 9V1	Ministry of Attorney General 2601 Lougheed Highway Sheriff Services Coquitlam , BC

Portion Inspected	Jobsite
	UNKNOWN
violations	NO ORDERS WRITTEN

Employer Representative Name	Accompanied By Employer Representative
Sean Praill	Sean Praill
Employer Representative Position	Accompanied By Worker Representative
Fleet Supervisor	Ray Tobjinski
Phone Number	Organization
604 927-2666	BCGEU
Signature	Officer of the Board / Signature
	SINGH, VEER

For Internal Use Only

Location not found

=====

Not sure of the correct location number and/or whether Sheriffs is also with firm number 4000. Please check and add accordingly.

Regulation(s) Referenced in Inspection Text

OHS 3.10

An employer who fails to comply with the Occupational Health & Safety Regulation or Board orders or directions is subject to sanctions as prescribed in the Workers Compensation Act.

Occupational Health & Safety Regulation requires that one copy of this report remain posted in a conspicuous place at or near the operation inspected for at least seven days, or until compliance has been achieved, whichever is the longer period.

An affected employer, worker, owner, supplier, union or member of a deceased worker's family may, within 90 calendar days of this report, in writing, request the Review Division of the WCB to conduct a review of an order, or the non-issuance of an order, in this report by contacting the Review Division at the Board's Richmond Office. The time limit may be extended in certain circumstances. Employers requiring assistance can contact the Employers' Advisers at 1-800-925-2233 --workers can contact the Workers' Advisers at 1-800-663-4261.

Date of Issue	Number	Number of Orders	Employer	Location	Classification Unit Number	Activity Time Recorded	Travel Time Recorded
2007-01-31	2007115520007	0	4000	002	841102	2.75	0.50

Inspection Text
-----------------

Issued on: 2007/01/31

Officer Inspection Text

On December 15th, 2006, a worker sustained a laceration to the top of his head while driving a Z-class prisoner transport vehicle. According to the worker, he struck his head on the overhead metal toggle switches when the truck drove over an uneven roadway, causing the worker to bump his head on the switches above. The worker sought medical treatment and was off work for a short period.

The officer met with the worker on December 22, 2006 to discuss his concerns.

The employer had conducted an investigation into the cause of the accident and taken appropriate measures for the prevention of the same. According to the employer, this particular truck was equipped with a seat that could be raised higher, it also had an exposed, overhead toggle switch mounted directly above the driver's seat.

The worker had the seat in the raised position, bringing him closer to the toggle switch.

According to the employer they are in a process of replacing the switch with a recessed type, such that the switches sit well recessed into the ceiling.

The employer also informed the officer that they are gradually replacing their fleet of vehicles, however, it may be a while before they are all replaced.

Employer Representative	Officer of the Board
Sean Praill	SINGH, VEER