

# TREE REMOVAL NOTIFICATION

Sunday, January 10, 2021

**The Urban Forestry Division received the following permit request to remove trees at the following location(s):**

**FROM:** Urban Forestry Division  
1149 S. Broadway, 4th Floor  
Los Angeles, CA 90015

**REQUESTER:** City of Los Angeles Bureau of Street Services  
1149 S Broadway 4th Floor  
Los Angeles, CA 90015

**PHONE NO:** (213) 847-3077

**REASON FOR REQUEST:** Citywide Sidewalk Repair Program

**MAIL STOP:** #550

**PERMIT TYPE:** No-Fee Permit

**SITE:** 1436

**TREE REPLACEMENT SIZE:** 24-inch box size

**CRM #** 1-460342221

**CEQA:** The tree removal(s) is/are (1) classified as operation, repair, maintenance or minor alteration of existing street, sidewalk, and gutter, involving negligible or no expansion of use beyond that previously existing; and does not involve the removal of a scenic resource; (2) the action is exempt under Article III, Section 1, Class 1, Category 3 (existing facilities - sidewalk repair or maintenance) of the City of Los Angeles Environmental Quality Act Guidelines (2002); and (3) none of the exceptions to the use of a categorical exemption as set forth in Section 15300.2 of the State CEQA Guidelines apply.

COUNCIL DISTRICT	ADDRESS	NO OF TREES IMPACTED	TREE SPECIES PROPOSED TO BE REMOVED	TREE REPLMNT QTY.	TREE REPLACENT SPECIES	REASON FOR REMOVAL
5	10707 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	Irreversible state of decline, severe canopy die-back, dead central leader limbs, and fruiting bodies at the base of trees.
5	10716 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10720 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10723 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10726 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10729 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10733 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10770 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10806 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10810 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10811 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10817 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10821 W Esther Av	1	Indian Laurel Fig (Ficus microcarpa)	2	Brisbane Box (Lophostemon confertus)	
5	10726 W Esther Av	1	Mexican Fan Palm (Washingtonia robusta)	2	Brisbane Box (Lophostemon confertus)	

**ALL ALTERNATIVES WERE CONSIDERED TO RETAIN THE TREES, i.e. SIDEWALK REDUCTION, RAMPING, ROOT PRUNING, MEANDERING INTO PRIVATE PROPERTY, AND BUMP-OUT (NOT COST-EFFECTIVE). TREE REMOVAL IS THE LAST OPTION WHEN THE ALTERNATIVES ARE NOT FEASIBLE. THEREFORE, TREES REQUIRE REMOVAL.**

### FOR BUREAU OF STREET SERVICES USE ONLY

The above request has been reviewed and approved.

The above request is denied.

**APPROVED BY:** \_\_\_\_\_

**DATE APPROVED:** \_\_\_\_\_