From time to time, Chesapeake receives safety alerts generated by sources outside the company. Please note that the statements in the attached alert are not made by Chesapeake and do not necessarily represent Chesapeake's position. Chesapeake shares these alerts as general information in an effort to minimize preventable incidents from occurring. Please review the attached alert from Genie and distribute it to all that may benefit.



## **Inspection Advisory**

## **Fall Protection Products with Yoke Snaphooks**

February 17, 2014


## **MSA Corporate Center**

1000 Cranberry Woods Drive Cranberry Township, PA 16066 800.MSA.2222 www.MSAsafety.com

## **Dear MSA Fall Protection Customer,**

We are issuing this *Inspection Advisory* to you, and apologize for any inconvenience that it may cause.

Yoke Industrial Corporation, the manufacturer of snaphooks used on many fall protection products industry wide, including MSA's, recently notified MSA of an issue involving the potential for missing or improperly installed rivets on Yoke snaphooks. Although the photographs below depict one snaphook model, other Yoke snaphook models are affected. The stamped "Y", as shown below, identifies the snaphook manufacturer.







**MSA Corporate Center** 

1000 Cranberry Woods Drive Cranberry Township, PA 16066 800.MSA.2222 www.MSAsafety.com

We are issuing this notice to you as a reminder to inspect the snaphooks on your fall protection products before each use as indicated in the instructions and inscribed on the snaphook. If any rivets are missing or if any rivets are not secured on both sides of the snaphook, immediately remove the fall protection product from service and contact MSA for replacement.

For additional information, you may access the supplier's *Product Notification* at the following link: <a href="http://www.yoke.net/english/index.asp">http://www.yoke.net/english/index.asp</a>. It includes a video describing the improved inspection process that Yoke has implemented as a result of this issue.

If you identify any snaphooks with missing or improperly installed rivets or you have any questions, please contact MSA Customer Service as follows:

- U.S., Canada, or U.S. Territories 1-866-672-0005 or by email at: <u>ProductSafetyNotices@MSAsafety.com</u>.
- Mexico 01-800-672-7222 or by email at: atencion.clientes@MSAsafety.com.
- Outside the U.S., Canada, Mexico, or U.S. Territories 724-776-8626 or by email at: LAMZonecs@MSAnet.com.

Again, we apologize for any inconvenience that this situation may cause; however, your safety and continued satisfaction with our products is most important to us.

Best regards,

Charles J. Seibel, Jr.

Manager of Product Safety