



1525 Hanover Street
 Hanover, MA 02339
 Phone 781-826-9755
 Fax 781-829-0240

www.aircleaningspecialistsne.com

of New England LLC

Preventive Maintenance and Service of Source Capture Vehicle Exhaust Removal System

Customer:	Fire Department Locations:	Vehicles
Central Falls Fire Department	Headquarters Station – 150 Illinois St.	4

Install Date:	Warranty Expire Date:

Contract Start Date:	Contract Expire Date:
March 1, 2016	February 28, 2017

Per station cost of service is \$148.00 initial vehicle, \$126.00 per additional vehicle attached to the Source Capture Vehicle Exhaust Removal System.

Total Number of Vehicles:	Frequency of Service:	Annual Cost of Service:
Four (4) Vehicles	Every six (6) months	\$1,052.00

Additional emergency service calls for mechanical failure of the system will be at no additional charge.

All prices are for service contract only and do not include parts out of warranty. For service contracts every twelve months there will be an hourly service charge. For service contract every six months there will be no hourly service charge.

As a Service Contract Customer all non warranty parts are discounted 6%.

Maintenance program applies to the items specified below.



1525 Hanover Street
 Hanover, MA 02339
 Phone 781-826-9755
 Fax 781-829-0240

of New England LLC

www.aircleaningspecialistsne.com

Preventive Maintenance and Service of Source Capture Vehicle Exhaust Removal System

Hose Inspection

- Hose clearance from ground
- Hose alignment
- Hose Condition

Nozzle Inspection

- Attachment on tailpipe
- Air line attachment to MFD Valve
- Nozzle condition

Safety Disconnect Inspection

- Rubber seal
- Aluminum fittings
- Debris screen

Track & Hardware Inspection

- Supports & hardware
- Track cleaning
- End stops
- Trolley condition & adjustments
- Balancer tension & adjustments

Compressed Air Supply Inspection

- Regulator condition & adjustment
- Air line and fittings
- Uncoupling Valve
- Manual fill valve
- Dryer

Air Compressor Inspection

- Drain tank
- Check oil
- Belt
- Regulator
- Check Pressure

Blower Inspection

- Lubricate motor
- Disconnect switch at fan

Ductwork System Inspection

- Joints and supports
- Stack and discharge cap

Control Panel Inspection

- Timer
- Sensor condition & adjustments
- Control relays
- Fuses

Reviewed per F.S.A. 4/22/16

Leonard Morganis
 Administration & Finance Officer

Date Submitted:

Submitted By:

[Signature]
 Air Cleaning Specialists

Date Accepted:

4-25-16

Accepted By:

[Signature]

Printed Name:

James A. Dioss

Approved as to form and correctness

[Signature]
 City Solicitor